## ROSCOMMON COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN COUNTY OF DOISONHADN

Dec. 28 10 27 AM \*93

For corners in

COMMISSION

Roscommon (County)		Located In:	Corner Code ##
1.	Public Land Survey	T <u>24N</u> R <u>4W</u> T R	L - 9
	Property Controlling in Section Miscellaneous Property in Sec.	T R S S T R S T R S T R R S T R R S T R R S T R R S T R R S T R R S T R R S T R R S T R R S T R R S T R R T R T R	

**ROSCOMMON COUNTY** PEER GROUP APPROVAL

Register of Deeds Stamp & File Number

DATE 12 - 14 - 1993

4. Lot No, Rec 5. Private Claims				A B
S. Trivate Glains			<del></del>	<sup>-</sup> 2   − 6
				3
				4 _ ,
Marvin E. Myers	n a field survey on	December	. 19 93	5
do hereby certify that under requir in lines 1 and 2 above were in co	ements of P.A. 74, Mic	higan P.A. of 1970, the	corner points mentioned	6 15
current manual of survey instructi	ons of the United Stat	tes Department of the	Interior, Bureau of Land	7
Management or by a decree of a Co	ourt of Law and/or that	the corner points me	ntioned in lines 3, 4 and 5	8
above were in conformance with t	he rules of the Michiga	an Board of Land Surv	reyors or by a Decree of a	ااو

expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Court of Law; established, re-established, monumented, re-monumented, recovered, found as

## 10 12

A. Description of original monument and accessories and/or subsequent restoration:

GLO - Aug. 1852 A.Brewer Mon. - Post WII: 11" W.Pine N65°E 22 lks. 10" W.Pine S33°W 28 lks.

July 1954 G.Henning Mon. - ½" Bar WIT: 'z" Bar East 33.00'

Oct. 1955 G.Henning Mon. - Shown not described

The Property of

L.284, pg.324 Nov. 1973 L.Cavanagh Mon. - Shown not described

L.305, pg.126 May 1975 L.Cavanagh Mon. - ½" Bar in Pav't Box

L.306, pg.81 June 1975 R.Higgins Mon. - 5" Bar

L.325, pg.627 Dec. 1976 F.Arleth Mon. - Fd. Pav't Box WIT: 14" B.Oak N47°W 37.50' 8" TW.B.Oak S20°W 59.30'

L.451, pg.407 Aug. 1984 F.Arleth Mon. - %" Bar in Pav't Box WIT: 14" B.Oak N47°W 37.50' 8" Tw.B.Oak S20°W 59.30'

June 1989 L.Cavanagh Mon. - Fd. ½" Iron WIT: 8" Poplar N80°W 43.79' 4" Poplar S40°W 74.01' P.P. S45°E 40.90'

L.558, pg.462 Sept. 1989 L.Cavanagh Mon. - Iron in Pav't Box WIT: 14" B.Oak N47°W 37.50' B" TW.B.Oak S20°W 59.30'

L.1, pg274 LCRC Sept. 1989 L.Cavanagh Mon. - Iron in Pav't Box WIT: 14" B.Oak N47°W 37.50' 8" B.Oak S20°W 59.30'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

Found PK nall in patched over 4" diameter pavement box with spike inside over spike over ½" bar and accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Mon. - Std. Roscommon County Monument in new pavement box WIT: Fd. Nail in NE Power Pole S37½°E 40.86'
Nail & tag NW face 6" Maple S42°W 77.18'
Nail & tag S. face 30" B.Oak N72°W 74.32'
Nail & tag NW face 10" Maple N52°E 68.77'



Date December 14.

31600 Surveyor's Michigan License No.

1993

December 21, 1993 Date

Peer Group Approved

FORM APPROVES BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

3 PAGE 51

LIBER