## STATE OF MICHIGAN COUNTY OF PISCHMON

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Dec. 28 10 27 All 193

For corners in CMMUSSION Roscommon Located In:

922£818 384

Port of War ! REGISTED A THE

Corner Code ## (County) T 24N R 4W Public Land Survey T \_\_\_\_ R \_\_ \_ R \_ T \_\_\_\_\_ R \_\_ Property Controlling \_ T \_\_\_\_ R \_\_ S \_\_\_\_ R \_ in Section S \_\_\_\_ R \_\_\_ Miscellaneous \_ R \_ Property in Sec. \_ T .

**ROSCOMMON COUNTY** PEER GROUP APPROVAL DATE 12-14-93

Register of Deeds Stamp & File Number

4. Lot No	, Recorded Plat			- A	В	С
<ol><li>Private Claims</li></ol>	·				T	
				2	<b>ხ</b> —	<b>—</b>
	·			3		Ĺ
			•	4	] 7—	$\Box$
. Marvin E. Myers	, in a field survey on	December	19 _ <sup>93</sup>	5		
	r requirements of P.A. 74, Michi re in conformance with regula	igan P.A. of 1970, the c		5	- B-	

current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

			• •		4 11		
2		[ 6—	5_	L.	] 3—	_2_	
3		<u> </u>	<b></b>		<del>                                     </del>		$\Box$
4	L	ļ	-8 -	<b>Ļ</b> ↓_	<u>                                     </u>	11	12
5		<u> </u>			_		
5	L.	  8—	17-	  16	  15	14	 13
7		1	$oxed{oxed}$				
8	L.	 19	20-		  22	23-	24
9	L	Ĺ	LÏ	LÏ		LĪ.	
10	L.	 30—	29	28	27_	26—	25
11				LΪ	$\perp \bar{\perp}$	LÏ.	
12	L	 31—	32	33	  34	35—	36
13	Ι '	Ĺ		<u>l ï</u>	<u> </u>		_ ĭ

A. Description of original monument and accessories and/or subsequent restoration: L.344, pg.223 April 1978 L.Cavanagh Mon. ½ " Bar WIT: 12" W.Oak S70°E 36.60' 14" B.Oak N40°E 52.62' Reg. of Deeds Mon. - %" Bar WIT: 12" W.oak S70°E 36.60' 14" B.Oak N40°E 52.62' 12" W.Oak N50°W 61.50' GLO - April 1839 J.Brinks Mon. - Post WIT: 8" Y.Pine S14½°W 18 lks. 9" Aspen N24°W 25 1ks. 12" W.Oak N50°W 61.50 GLO - June 1852 W. Burt Jan. 1991 L.Cavanagh Mont - ½ Bar-WIT: 7" R.Oak N34°W 41.35'. Mon. - Fd. Post WIT: 10" Y.Pine S79°E 17 1ks. L.304, pg.219 May 1975 L.Cavanagh Mon. - ½" Bar 15" R.Oak N38°E 52.50! 12" W.Oak S79°E 36.50! Nov. 10, 1945 G.Henning Mon. - 2" Ba WIT: 10" W.Oak N27"W 62.00' 6" B.Oak N37°E 53.00' Dec. 1924 G.Delmater Mon. - Iron @ Cor. Fd. Post WIT: 12" Y.Pine West 57.50' Nov. 1945 G.Delmater same as above

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

Found  $\frac{1}{2}$ " x 30" Bar verified position by measurement to accessories of record and accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Mon. - Std. 21" x 2" Roscommon County Monument WIT: Spike NW side 18" R.Oak N42°E 53.12'
Spike N side 12" W.Oak S69°E 36.61'
Nail & tag SE face 9" Maple S52°W 12.02'
Spike NE side 9" R.Oak N31°W 41.57'
2" Well point N88°W 22.28'

December 14, 1993



_	~	
Signed by Many E.	my	Date December 21, 1993
Surveyor's Michigan License No	31600	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
Date December 14, 1993	Peer Group Approved	REVISED MAY 14, 1975 Revised Jan., 1983

Peer Group Approved

3 PAGE 52 LIBER