APPROVED BY	PEER (	GROUP
P.A. 345	OF 1990	)

## 1999 REMONUMENTATION PROGRAM

## LAND CORNER RECORDATION CERTIFICATE

1999 SEP 30 A 8: 09

For co	SAGINAW COUNTY Filing Requirement of Act 74, Mich. P.A. 1970		SAI	GINAW	D M, D( R OF D COUNT	IEEDS Trimil	•
Sagin (Coun	aw Located In: Corner Code # y) Chapin Twp.		2144	PACE 1	1445	j	٠.
<ol> <li>Pub</li> <li>Proj in S</li> <li>Miso Proj</li> </ol>	lic Land Survey  T 9N R1E G-10  T R  Perty Controlling S T R  ection S T R  cellaneous S T R  perty in Sec. S T R	of Deed	s Stam	p & File	e Numb	er	
4. Lot	No, Recorded Plat	:		E F	<b>Б</b> Н		Ι ΄
5. Priv	ate Claims	6	5	4	3	2	1
ŀ,	John H. Rauser,P.S. , in a field survey on <u>September 28</u> 19 <u>99</u> . <sub>5</sub>	7	8	9	10	וו	12
do here in lines	by certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  1 and 2 above were in conformance with regulations and rules therefore as required in the  manual of survey instructions of the United States Department of the Interior, Bureau of Land  7	18	17	16	15	14	13
Manager above v	ment or solvey institutions of the officer States Department of the interior, pureau of Land 7 ment or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 vere in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a f Law; established, re-established, monumented, re-monumented, recovered, found as 9	19	20	21	22	23	24
expresse	ed below:	30	29	28	27	26	25
NOTE:	Not more than 2 corners, all in the same town and range, may be recorded on this 12 certificate.	31	32	33	34	35	36
<b>A.</b> G-10	Description of original monument and accessories and/or subsequent restored 1/4 Corner, Sections 27 & 28, Chapin Township		dende Vrasel	2 m			- <del> </del>
	1831 GLO wood post placed by Robinson Thomas, D.S. Beech 12" S86W 12lks (7.92')			A. A. C.	⊌ § 20	100	
	Lynn 11" N15E 9lks (5.94')  Found no subsequent record of perpetuation or restoration			SEC	TION	<b>A</b>	
В.	Description of corner evidence found and/or method applied in restoring or a	reestal	olishin	ıg corn	ier:		
<u>G-10</u>	1/4 Corner, Sections 27 & 28, Chapin Township  Found no evidence of the original government accessories. Found no object at this of the corner by doubling the distance between the found stake and stones at G-11 the 1/8 corner between G-11 and G-10. The distance being 1319.99', doubled is 2658.12'. The occupation West at the approximate 1/8 line between G-10 and G-9 r a drain West and 1332.9' to a fence line along the North top of bank of this drain from split of the distance between G-10 and G-9 = 1329.06', which falls between the center of bank. Measured East from G-10 to the occupied line along the N-S 1/4 line (a 1/1-10) 2639.66', the occupation to the East at the 1/8 line between G-10 and H-10 mear road at said occupied N-S 1/4 line is 2.7' South of a line between G-10 and I-10. vicinity of this corner. We recommend that the calculated position of G-10 be perpetuation of the position of the original corner and be monumented with a stand brass cap in a monument box.	and the 2639.5 measure this caperline of the caperline of	ne foun 98'. M led, 13 llculate f drain road e 1319.1 no col oted as	ed stone leasure 16.7' to ed posit and the xists be 9'. The inflictings a car	e and c to North the ce tion of G e fence tween cetween g evider reful ar	rockery h to G-t nterline G-10. T at the t G-10 a rline of t nce in t	y at 9 = of he top and the oful
_	Description of management for a managed account of the late of the						

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

<u>G-10 1/4</u>	<u> 1 Corner,</u>	Sections 27	<u>&amp; 28,</u>	<u>Chapin</u>	Township
-----------------	-------------------	-------------	------------------	---------------	----------

Set 5/8" re-rod with standard Saginaw County brass cap stamped "G-10 39096" and monument box.

13.95' T/C North end 18" CMP East

21.40' South edge stop sign post S80E

43.45' Set chisled "+" T/C South end 18" concrete culvert S30E

S50W 21.25' 1/2" re-rod with ROWE traverse cap

S60W 23.20' North edge of North leg double arrow "<-->" sign post

Signed by Surveyor's Michigan License No. 39096

