🕏 🕻 📞 ۋېۋېلىلى ئارغايىيى د مىلىپ

APPROVED BY PEER GROUP P.A. 345 OF 1990 SARINAW COUNTY

SECTION

LIBER 2084 PAGE 241

SAGINAW COUNTY REMONUMENTATION

SOSINAW COUNTY	SAGINAW COUNTY REMOVEMENT
31 9-16-98	LAND CORNER RECORDATION CE

510 7-10 70		LAND CORNE	R RECORDATION CERT ment of Act 74, Mich. P./	A. 1970 왕교 등
For	SAGINAW (County)	Located in: BRADY TWP	Corner Code #	PRDED/FII OCT -5 A
1.	Public Land Survey	T <u>9N_R3E</u> TR	<u>B-13</u>	A 9: 5
2.	Property Controlling in Section	STR STR		
3.	Miscellaneous Property in Sec.	STR STR		Register of Deeds Stamp & File Number

4.	Lot No, Recorded Plat
5.	Private Claims

, 19<u>98</u> do hereby state that , in a field survey on SEPTEMBER 25 under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Menagement or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

Not more than 2 corners, all in the same town and range, may be recorded NOTE: on this certificate.

A				. E	F	G	i H		J	К	L	_м
וֹ י	Ī	Ī	Ī	\Box	T	Ţ		\Box	\neg			
2	6	\dashv	—	\dashv	- {	\dashv	— <u>3</u>	1	— 2 1	\dashv	- i	٦
3												\dashv
			_		_ J		I		 11		12	
4	_ ′			i	_ i		1				1	1
5					_†				_		\neg	
6	ŀ١	å —	۱ ا	7	— 1è	<u> </u>	<u>ا</u> ا	5 —	<u>ا</u> ا	-	- 1	3 —
7		<u> </u>								<u> </u>		
]	ļ	١.				_ 2	<u> </u>	_ 2	ا_ا	_ ,	
8	┝'	ទ — រ	Γ	٥٦	21		Γí	ĺ	-	Ĭ	١٦	
9	-	├	 	_	_		-	_				
10	<u></u> -₃	ю —	- -2	9 —	— 2	ė —	 2	7	 2	6	- 2	5 —
	L	<u>L</u>		<u> </u>	_ !	<u> </u>	ļ	<u> </u>	<u> </u>	ļ	<u> </u>	<u> </u>
31					ŀ	1		1_	L.	_	L.	<u> </u>
12	1	ıı	Τ;	32 l	3	3 	T	;, 	T 3	15 —]] - ,	ւն — }
13	L-,	•	I	<u></u>	L		т.			_		

- Description of original monument and accessories and/or subsequent restoration:
- WOOD POST SET BY JOHN MULLETT, DEPUTY SURVEYOR, IN 1840 5" HICKORY S88°E 6 1/2 LINKS 20" MAPLE S26°E 22 LINKS NO EVIDENCE OF THIS CORNER REMAINS NO LCRC'S OR SURVEYS RECORDED FOR THIS CORNER
- Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - SET CORNER BY GLO PRORATION BETWEEN A-13 AND C-13 CORNER SET ON LINE B-13 EXTENDED THROUGH B-1, T8N-R3E

FOUND CORNER SET BY SPICER ENGINEERING AT SPLIT BETWEEN A-13 AND C-13. PEER GROUP DID NOT AGREE WITH THIS LOCATION. FOUND POINT, 1" IRON BAR, IS 13.49 FEET EAST OF NEW LOCATION.

ACCEPTED AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE ORIGINAL CORNER.

- Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - SET 5/8" STEEL BAR WITH 3" BRASS SAGINAW COUNTY REMONUMENTATION CAP IN MONUMENT BOX B-13

SET NAIL & SHINER IN E END 14" CMP S50°E 47.91'

SET NAIL & SHINER IN W END 14" CMP N47°W 50.38'

N70ºE 38.35' SET 1/2" ROD W/CAP 26454

CHISELED + TOP CTR CONC HEADWALL S10°W 45.15'

1/2" ROD USED AS B-1, T8N-R3E WEST 8.49'

Signed by Surveyor's Michigan License No

LAND

REVISED OCT., 1995

MC

OF

BRIAN D

FENGUEUN

ii...