LIBER 1986 PAGE 510 APPROVED BY PEER GROUP SAGINAW COUNTY REMONUMENTATION PROJECT Liber 7 Page 95 SAGINAW COUNTY LAND CORNER RECORDATION CERTIFICATE MILDRED M. DODAK REGISTER OF DEED! SACINAY COUNTY MIC Filing Requirement of Act 74, Mich. P.A. 1970 RECORDED & FILED For corners in Saginaw County Located In: Corner Code # Chesaning Township 1. Public Land Survey 9N R 3E G-6 R 2. Property Controlling R in Section R Miscellaneous Register of Deeds Stamp & File Number Property in Sec. 4. Lot No. , Recorded Plat <sub>T</sub> A С D E HIJKL 5. Private Claims 2 5 3 2 6 ---1---3 John H. Rauser , in a field survey on February 14, 4 7 Я Q 10 11 12 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land 18 17 ി6 🍅 15 14 13 Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 7 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a .10 Court of Law; established, re-established, monumented, re-monumented, recovered, found as 20 23 24 expressed below: 9 10 30 29 28 -27 25 NOTE: Not more than 4 corners, all in the same town and range, may be recorded 26 on this certificate. 11 12 31 32 33 34 35 36 Description of original monument and accessories and/or subsequent restoration: 1/4 Corner, Section 15 & 16, T9N-R3E Wood post placed by J. Mullett, D.S. in 1840 during Subdivision of Big Rock Reserve S53°E 5 lks. (3.3') 6" W.Oak N68°W 22 lks. (14.52') 7" W.Oak 1851, Plat of the Village of Chesaning L.G.P.561, Andrew Huggins Surveyor 1949, Spicer Engineering field notes, find 6" complete tile on end 3.5 feet below gravel surface witnessed and set 3/4" x 20" iron pipe directly above.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

## G-6 1/4 Corner, Section 15 & 16, T9N-R3E

В.

Find no evidence of Original Government Survey. Find 3/4" pipe in asphalt shoulder 13'± West of C.L of asphalt roadway. Verified pipe with 1949 Spicer Engineering field notes M=106.40' (R=106.43') to SE corner brick house. Found monument also in agreement with more recent records as stated in "A" above and is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

## G-6 1/4 Corner, Section 15 & 16, T9N-R3E

Place 5/8" Re-Rod w/"Saginaw County Monument" Brass Cap Stamped P.S. 39096 and Monument Box

witnessed and set 3/4" x 20" iron pipe directly above.

1955, unrecorded survey by Spicer Engineering Co. for Henry Haeske

1977, unrecorded survey by Spicer Engineering Co. job no.19227, fnd corner

1977, L.C.R.C by J.W.Martin, P.S. #4699 rec. L.4,P.74 Saginaw Co. Records

1989, Act 132 survey by M.L. Vanraemonck, P.S.#24622 rec. L.1767,P.59 Saginaw Co. Records

1990, Act 132 survey by M.L. Vanraemdonck, P.S.#24622 rec. L.1775,P.208 Saginaw Co. Records

1990, Act 132 survey by N.C.Caldwell, P.S.#12018 rec. L.1781,P.1161, Saginaw Co. Records

1993, Act 132 survey by M.L. Vanraemdonck, P.S.#24622 rec. L.1873,P.183 Saginaw Co. Records

1994, Act 132 survey by M.L. Vanraemdonck, P.S.#24622 rec. L.1912,P.490 Saginaw Co. Records

\$45°W 21.28' Set PK W/tag #39096 SE fce. T/P N45°W 54.86' Set PK W/tag #39096 W fce. T/P

S75°E 82.48' Set PK w/tag #39096 S fce U/P N75°E 67.40' Set PK w/tag #39096 S fce. T/P

106.40' SE corner brick house (R=106.43')

Signed by

Date

SURVEYOR MO29

PESSIONA REVISED MAY 14, 1975 REVISED JAN., 1983

Surveyor's Michigan License No.

ADAPTED FOR WORD PROCESSING MARCH, 1993

MAY 1 5 1837

MARIL C

OF MICHIGAN ₹E JOHN H. RAUSER PROFESSIONAL 36098