## SAGINAW COUNTY RE-MON 1997 LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

ERECORDED& FILED

For comers in Taymouth Township	SEP 25 3 23 PH 197
Saginaw Located In: Corner Code #	der en a sa Lu . fil
1. Public Land Survey	MILDRED M. DODAK REGISTER OF DEEDS SAGINAW COUNTY MICH.  LIBER 2027 PAGE
2. Property Controlling       S T R	Suber 7 Page 138 Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	ABCDEFGHJKL
I, Ronald C. Prevost, in a field survey on	1
established, re-established, monumented, recovered, found as expressed below:  NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	8 19 20 21 22 23 24 9 10 30 29 28 27 26 25 11 12 31 32 33 34 35 36
A. Description of original monument and accessories and/or subsequent restoration:	23
L.C.R.C. L1-P256, Martin, 1972 3/4" pipe. L.C.R.C. L4-P2, Tommer, 1976 3/4" pipe in mon box.	PROVED BY PEER GROUP P.A. 345 OF 1990 SAGINAW COUNTY
B. Description of corner evidence found and/or method applied in restoring or reestablishing	corner:
E-13 Found 3/4" pipe in mon box 4-30-97. L1-P256, S.36.55 nail W. face 20" Oak (M 36.40) L1-P256, NE 53.35 to face 18" Pine (M 53.58 to nail S face) L4-P2, S.36.40 nail & tag W edge 12" Oak (M 36.40) Approved by Peer Group 8-28-97.	SURVEY & EMONUMENTATION MAR 1 8 1998
	SECTION
C. Description of monument for corner and accessories established to perpetuate locating the	position of the corner;
E-13 Replaced 3/4" pipe with 5/8" re-rod, Sag. Co. cap in ex. mon box 9-9-97. South 36.40 nail & tag W. side 20" Oak. N.40°E, 53.58 nail S face 18" Pine. N.40°W. 34.91 nail & cap E. side 18" Pine. N.05°W. 29.15 nail & cap E. side 18" Pine.	PROFESSIONAL SURVEYOR  NO. 24612
Signed by Ronald C. Prevost  Date_	9-25-97
Surveyor's Michigan License No. 24612	