

LAND CORNER RECORDATION CERTIFICATE RECORDED/FILED
 Filing Requirement of Act 74, Mich. P.A. 1970

For corners in **SAGINAW COUNTY REMONUMENTATION**

1997 SEP 26 P 3: 26

<u>SAGINAW</u> (County)	Located in: <u>B'RUN TWP.</u>	Corner Code #
1. Public Land Survey	<u>T 10N R 6E</u>	<u>M-6</u>
	<u>T</u> <u>R</u>	
2. Property Controlling in Section	<u>S</u> <u>T</u> <u>R</u>	
	<u>S</u> <u>T</u> <u>R</u>	
3. Miscellaneous Property in Sec.	<u>S</u> <u>T</u> <u>R</u>	
	<u>S</u> <u>T</u> <u>R</u>	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

MILDRED H. DODAK
 REGISTER OF DEEDS
 SAGINAW COUNTY, MI.

LIBER 2027 PAGE 454

Liber 7 Page 175
 Register of Deeds Stamp & File Number

I, BRIAN D FERGUSON, in a field survey on JUNE 17, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

M-6: WOOD POST SET BY WAMPLER IN 1822

APPROVED BY PEER GROUP
 P.A. 345 OF 1990
 SAGINAW COUNTY

9-18-97 BDF

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

**M-6: FOUND 3/4" IRON ROD
 SURVEY RECORDED IN L 1373 PG 698**


**ACCEPTED BY THE PEER REVIEW GROUP AS THE BEST
 AVAILABLE EVIDENCE OF THE POSITION OF THE ORIGINAL CORNER**

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

**M-6: SET 5/8" ROD W/3" BRASS CAP IN MONUMENT BOX
 WEST 36.84' E. FCE 16" ASH TREE
 N45W 37.17' SE FCE 8" BIRCH TREE
 S30E 26.04' 1/2" REBAR
 N30E 25.78' 1/2" REBAR**

Signed by *Brian D Ferguson*
 Surveyor's Michigan License No. SURVEY & 26454
REMONUMENTATION

Date SEPTEMBER 25, 1997



MAR 18 1998

SECTION