

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

FOR CORNERS OF--:	LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. <u>11</u> N. R. <u>3</u> E. <u>K</u>	<u>D-12 D-11</u>
2. PROPERTY CONTROLLING IN SECTION	T. _____ N. S. R. _____ E. W.	_____
3. MISCELLANEOUS PROPERTY IN SECTION	T. _____ N. S. R. _____ E. W.	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

Saginaw County

REGISTER OF DEEDS STAMP AND FILING NUMBER

W

I, Dwayne Scott, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on October, 1976, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on October, 1976, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

<p>D-12 Corner recovered with witnesses from M.D.S.H. Placed 1/2" I.P. with plastic cap #12029</p>	<p>D-11 Recovered in bituminous surface. Found with notes from Spicer Engineering, a Survey firm located in Saginaw, MI</p>
---	--

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

<p>D-12 1/2" iron pipe with cap #12029 S.89°W. 70.00' 48" oak Sp. and tag N.13°E. 57.30' telephone pole P.K. & tag S.05°E. 34.81' power pole P.K. & tag S.80°E. 20.20' W. edge of W. rail at Rd. G</p>	<p>D-11 Nail in bituminous surface N.W. 126.80' S.E. corner house S.W. 117.52' N.E. corner of office of green house On old fence line to East</p>
---	---

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12029 (SEAL)

FOR STATE AND UNITED STATES AGENCIES.

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. 12029