LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

| FOR CORNERS OF -: LOCATED IN -: | CORNER CODE NUMBER | Sayinaw Co |
|---|---|--|
| 1. PUBLIC LAND SURVEY 11 T. 11 N. R. 4 | E. J-5, K-4 | 3ag/na w |
| 2. PROPERTY CONTROLL- ING IN SECTION, T N. S., R | E. W | |
| 3. MISCELLANEOUS N. PROPERTY IN SECTION T. T. T. S., R | E. | |
| 4. LOT NO, RECORDED PLAT | | |
| 5. PRIVATE CLAIMS | | REGISTER OF DEEDS STAMP AND FILING NUMBER |
| I, | ed or restored as expressed below and of survey instructions of the United St t of law. Furthermore, that the corner, 19, found, recovered, rest of the Michigan State Board of Registr | in conformance with regulations tates Department of the Interior, points mentioned in lines 3, 4 ored, established |
| B. Description of corner evidence found and/or methods. J-5 Sk Cor. Sec. 11 Found 1k" pipe. | od applied in restoring or re-establishin K-4 E ¹ g Cor. Sec. 11 Found iron in mon. bo | |
| C. Description of monument for corner and accessorie | es established to perpetuate locating the | position of the corner: |
| J-5 S ¹ 4 Cor. Sec. 11 11/4" pipe at top of bank on West edge of ditch. S45°W - 1.25' - 6" Oak S10°W -13.87' -10" Ash N28°W -14.24' - 8" Ash S80°W -41.40' -15" Ash Spikes & ref. tags in trees. | | |
| SIGNED BY | DATE | |
| SURVEYOR'S MICHIGAN REGISTRATION NO | | (SEAL) |
| FOR STATE AND UNITED STATES AGENCIES: | | OF MODE. |
| SIGNED BY | DATE | Engalp. |
| APPROVED AND SIGNED BY MICHIGAN REGIS | DATE STERED LAND SURVEYOR | 7-29-84 (ELIPERA) (A) |
| SURVEYOR'S MICHIGAN REGISTRATION NO | 18655 FORM APPROVED BY MICHIGAN STATE BOA | RD OF THE PHANTION JAN. 28. 1971 |