				$g_{ij} \ll \frac{1}{2}$	
APPROVED BY PEER GROUP P.A. 345 OF 1990 SACINAW COUNTY B-3/-94 For corners in SURVEY & SacinaMONUMENTATION		Saginaw County Remonumentation  LAND CORNER RECORDATION CERTIFICATE  Filing Requirement of Act 74, Mich. P.A. 1970  ated In: Corner Code ##		Miller La (FAAD, Which	
2.	COMMISSION T T Property Controlling S T in Section S T Miscellaneous S T	R	M 5	NOV 28 10 23 AH '94  MILDREL A JOUAK REGISTER OF BEEDS SAGINAW COUNTY MICH.  gister of Deeds Stamp & File Number	
I, <u>Cur</u> do in l cur Ma abo exp	Craig W. McVean, in a field sur hereby certify that under requirements of Pulines 1 and 2 above were in conformance rrent manual of survey instructions of the Unagement or by a decree of a Court of Law and over were in conformance with the rules of the unt of Law; established, re-established, pressed below:  OTE: Not more than 4 corners, all in the continuous of the unit of the conformance with the rules of the unit of Law; established, re-established, pressed below:  OTE: Not more than 4 corners, all in the continuous of the unit on this certificate.  Description of original monument and M.5 Set Post J. Wampler - 1822.  Ash 20" South 12 Lks.  Pine 18" N 46° W 17 Lks.  SCRC witness card - iron post 6" below LCRC - L. 1, P. 67 - Found 3/4" pipe - Les SCRC witness card - 3/4" iron pipe 1982.	vey on June 21 A 74, Michigan P.A of 19 with regulations and rul inited States Departmen ind/or that the corner poi ie Michigan Board of Lar monumented, re-monu the same town and ra d accessories and/or  road - 1926. ach - 1971.	19 _94	A B C D E F G H I J K L  2 6 5 4 3 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
B	Description of corner evidence found M5 Standard corner common to Section Found 3/4" internal diameter (1" outer diabox per SCRC, LCRC, and recorded surr Road. Agrees with GLO distance S. to A accepted as the best available evidence original corner.	n 12 and 13, T12N, R2E ameter) iron pipe in mon veys at N. edge of Fros 5-T12N-R3E. Monumen	• • •	corner:	
C.	Description of monument for corner a	ind accessories estat	olished to perpetuate locating the	e position of the corner:	

AOFESSIONA Date 11-16-99 Surveyor's Michigan License No. \_

 $\underline{\text{M 5}}$  Replace 3/4" I.D. x 12" iron pipe with 2-1/2" Saginaw County brass cap on 5/8" rebar in mon. box. S 45° E (-R) 45.13' (44.95' - SCRC) to Found Nail and shiner in SW.

side U.F.
N 63° E 29.23' to capped 3/8" rebar.
S 21° W 106.25' to nail and tag in E. side 12" box elder.
S 13° E 74.70' (74.56'-SCRC) to set nail and tag in W. side U.P.
N 45° W 39.48' to pk and tag in 12" CMP.
South 19.91' (19.82' & 19.90'-R, 19.80' SCRC and GLO) to A 5-

side U.P.

T12N-R3E.

OF MICHIGAN

CRAIG W.

MCVEAN PROFESSIONAL SURVEYOR No. 39088