	. ,	
1. Public LATE MONUMENTATION T APR 2 4 1995 T 2. Property Controlling S T	Saginaw County Remonumental LAND CORNER RECORDATION CERT Filing Requirement of Act 74, Mich. F cated In: Corner Code ## Cated In: A 12 R	TIFICATE LIBER 6 PAGE 245
in Section COMMISSION 3. Miscellaneous S T Property in Sec. S T 4. Lot No, Recorded Plat 5. Private Claims	R	Register of Deeds Stamp & File Number A B C D E F G H I J K L I
do hereby certify that under requirements of P. in lines 1 and 2 above were in conformance current manual of survey instructions of the L Management or by a decree of a Court of Law a above were in conformance with the rules of the Court of Law; established, re-established, expressed below: NOTE: Not more than 4 corners, all in on this certificate.	rvey on	ioned in the 7
A. Description of original monument and A 12 Not set in original GLO survey. LCRC - L. 2, P. 254 - 1" U-shaped bar - 1 LCRC - L. 1721, P. 221-222 - found 1/2" Recorded Survey - L. 1565, P. 905 - 1" in	Martin - 1974. rod - Ledy - 1988.	.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A 12 Closing 1/4 corner common to Section 31, T12N, R3E found 1-1/2" x 3/4" x 14" long iron with U-shaped top per LCRC L. 2, P. 254 and recorded survey 0.16' W. of standard line. Monument 0.04' S. of split distance between A 13 and A 11. Monument accepted as the best available evidence of the position of the corner.

Reference Pt "B" - Found 1/2" rod per LCRC L. 1721, P. 221 and 222 - 11.18' S. of A 12. This monument was established by McKelvey per LCRC L. 2, P. 85 - 1972 as M 12-T12N-R2E not as A 12. Monument was established using improper procedures and is not utilized as A 12-T12N-R3E in this survey. 1/2" rod replaced with pk nail.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A 12 Replace 1-1/2" x 3/4" x 14" iron with 2-1/2" Saginaw County brass cap on 5/8" x 18" rebar in mon. box on standard line.

N 25° E 24.17' to capped 3/8" rebar.

N 15° W 122.37' to nail and tag in E. side 12" Pine.

N 18° W 52.23' (51.08' -M, 51.13' -R to face) to chiseled "x" on E. side concrete M.H.

S 18° E 38.65' to capped 3/8" rebar.

South 12.40' to M 12-T12N-R2E.

South 11.18' to Reference Pt "B".

CRAIG W.
McVEAN
PROFESSIONAL
SURVEYOR
NO.
39088

Signed by Crung M. Malean
Surveyor's Michigan License No. 39088

12/17/94