P.A. 345 OF 1990	ER 1 989 PAGE 22 87	Li	ber 7	Pag	e l
10-23-96 SIA LAND CORNER Filing Requirem	NTY REMONUMENTA RECORDATION CERTIS nent of Act 74, Mich. P.A.	ELCATE		C	,
Saginaw JAOMAS Tu			MIL REGI SAGIN	Oct :	, 500 M
1. Public Land Survey	(B-7) C-7	÷	LORED M. DO NSTER OF D NAW COUNTY	153 153	BECORDED & FILED
2. Property Controlling S T R IN Section			EEDS MICH.	CON CON CON CON CON CON CON CON CON CON	
4. Lot No, Recorded Plat 5. Private Claims		Regist	er of Deeds S	tamp & Fil	e Numb
I, <u>Duane F. Ledy</u> , in a field survey on <u>October 30</u> , 1 requirements of P.A. 74, Michigan P.A. of 1970, the corner points mention conformance with regulations and rules therefore as required in the current in United States Department of the Interior, Bureau of Land Management or by that the corner points mentioned in lines 3, 4 and 5 above were in conformal Board of Land Surveyors or by a Decrea of a state of the sta	led in lines 1 and 2 above were in nanual of survey instructions of the a decree of a Court of Law and /or	5	D E F 5 4	G F I	J K 2
Board of Land Surveyors or by a Decree of a Court of Law; establishing recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may on this certificate.	ed, re-established, monumented,	7 8 —19 9 10 —30 11 12 —31	-29 -28 - -32 -33	22 - 2 -27 - 2 -34 - 3	32:
A. Description of original monument and accessories and/or subse B-7 Set post at 40.00 chains West of C-7; 1822, Joseph Wampler 7" Ash-S88°E, 26 links 10" Elm-N84°W, 14 links -Survey (L1954, P1114,5) 1995, Wade-Trim, set 3/8" rod/cap.	Set post at 80.00 cha 7" Sycamore-N38°W -L.C.R.CMartin (L1, -Survey (L1352, P41, -Survey (L1666, P18, -Survey (L1954, P11, pipe/cap #24	, 21 links 4 . P257) 1972; 5) 1971, same 4) Ledy 1984; 14,5) 1995, W 612	30" Ash-S75°i 3/4" pipe as L.C.R.C. found 3/4" p ade-Trim, fou	E, 4 links	pler
B. Description of corner evidence found and/or method applied in method 3/8" Rod w/cap #39088 per Survey (L1954, P1114,5) remaining witnesses: S13°E, 135.38' (135.12' M) chisled X on NE cor. conc. pad S55°E, 114.75' (114.45' M) N & T in SW side 5" Oak N45°E, 154.52' (154.33' M) N & T in NW side 24" Oak Monument accepted as best evidence of original position.	estoring or reestablishing corr C-7 Found 3/4' -L.C.R.C. (L1, P257) Oak (found S85°W 16" Oak (fnd S25°E -Survey (L1666, P184 N 46.59' to nail in -Survey (L1954, P111 Maple; N62°E, 47.0 Monument accepted a	50.00 (C13), 59.6' to scar , 75.2' scar for); S 43.00' to 40" Oak (fnd: 4,5) N30°E, 5	fce 28" Oak) e 24" twn Oal nail in 30" Oa at 46.6") .99' (5.97' M)	; SE 75.2' k) ak (fnd at 4 n&t in W/s	fce twn 3.00')
C. Description of monument for corner and accessories established to B-7 Set 5/8" rod with remon. cap NNE 86.85' to nail in West side 6" Poplar S13°E 135.12' to chisled X in NE corner concrete pad S55°E 114.45' to Nail & Tag in SW side 5" Oak NE 154.33' to Nail & Tag in NW side 24" Oak	Set 5/8" rod with remo NE 5.97' to nail in W SW 43.00' to nail in E NE 47.08' to nail & ta East 36.54' to nail in N	n cap over 3/4 est side 3" Ma ast side 20" O g in SE side 1	" pipe, ple clump ak 2" Manla		
Signed by Marane Fledy	Date	<u>31/96</u>	GAREOF M GAREOF DUANE LEDY PROFESSI SURVEY	ONAL *	
Surveyor's Michigan License No. 21575	-	THE STATE OF THE S	No. 2157		<u> </u>
PAY 1 C 1 M 1	FORM APPROVED BY MICHIGAN S	FTATE BOARD OF P	ROFESSIONAL SU	RVEYORS, JAN REVISED MAY REVISED J REVISED O	14,1975 AN 1983

13