APPROVED BY PEER GROUP

P.A. 345 OF 1990 SAGINAW COUNTY A

SAGINAW COUNTY REMONUMENTATION DEC 27

FILEP 1 44 PM *95

12/6/95	BIH
For corners in	- t

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

REGISTER OF DEEDS SACINAW COUNTY MICH.

SAGINAW Located In: Corner Code ## (County) THOMAS TOWNSHIP 1. Public Land Survey T_12NR_3E T 12NR 3E G-13 __ R _ ONUMENTATION R Property Controlling . R in Section S Т _ R . Miscellaneous FEB 2 2 1996 Property in Sec. _. R

Lilev 7

Register of Deeds Stamp & File Number

COMMISSION _ , Recorded Plat __ Private Claims __

Brian D Ferguson , in a field survey on __ December, 18 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

8 9 10 11 12

A. Description of original monument and accessories and/or subsequent restoration:

F-13 Wood post set by J. Wampler, Deputy Surveyor 1822. LCRC recorded in 1977 in L 4, Pg 55

G-13 Wood post set by J. Wampler, Deputy Surveyor 1822. LCRC recorded in 1971, L. 1 Pg 90. All witnesses gone

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F-13 Found no evidence of original government corner. Found 3/4" pipe

G-13 Found no evidence of original government corner. Set 3" brass disk at average location of re-tracement of 4 different survey by 4 different surveyors.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3" Brass Disk East, 69.05', F-1 T11N-R3E, 3" Brass Disk North, 50.53', Spike E fce 15" Poplar N. 60° W., 16.05', Spike S fsce 6" Poplar S. 40° W., 67.18', Spike E fce 30" Oak

3" Brass Disk East, 119.23', G-1 T11N-R3E, 3" Brass Disk West, 39.55', E fce 6" steel gate post S. 35° E., 48.53', Spike N fce 8" Cedar N. 15° W., 12.50', Spike E fce 10" Pine

Surveyor's Michigan License No.

___ Date __

BRIAN D FERGUSON LAND

ΑL

OF

26454 FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYS