APPROVED BY PEER GROUP

Property in Sec.

expressed below:

P.A. 345 OF 1990 SAGINAW_COUNTY

SAGINAW COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

| 45 PH '95 Dec. 27

Maddida a coak Registratibeeds SACINAW COUNTY MICH.

Fo	r corners in		
	SAGINAW	Located In:	Corner Code ##
	(County)		
			THOMAS TOWNSHIP
1.	Public Land Survey	т _12N R _3E	H-13
	•	T <u>12N</u> R <u>3E</u>	(1-13)

ONUMENTATION _ R: -::-2. Property Controlling __ T _____R _ in Section S. R т 3. Miscellaneous FEB 2 2 1996

Liber 7 Page 13

Register of Deeds Stamp & File Number

COMMISSION _ , Recorded Plat _____ 4. Lot No. 5. Private Claims ___

Brian D Ferguson , in a field survey on _ December, 18 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

... R .

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10 11 12 13

A. Description of original monument and accessories and/or subsequent restoration:

H-13 Wood post set by J. Wampler, Deputy Surveyor 1822. LCRC recorded in 1972 in L 1 Pge 257

I-13 Wood post set by J. Wampler, Deputy Surveyor 1822.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

H-13 Found no evidence of original government corner. Found 3/4" at location per Spicer Survey in L 1377 Pg 1195. Monument is accepted as the best available evidence of the position of the original corner.

Found no evidence of original government corner. Found 3/8" rod in rocks and glass. Monument is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-13 3" Brass Disk East, 27.59', Nail & cap W. fce 15" Twin Maple S. 60° E., 48.10', Nail & cap N fce 8x8 post N. 45° E., 47.46', Nail & cap E fce 18" Ash East, 61.67', H-1 T11N-R3E, 3" Brass Disk

3" Brass Disk in Monument Box 1-13 East, 34.94', I-1 T11N-R3E, 3" Brass Disk S. 25° E., 13.03', Spike in N fce pwr pole N. 50° E., 7.46', PK nail NW fce pwr pole N. 85° W., 40.78', Nail & disk S fce pwr pole

Surveyor's Michigan License No.

_ Date _

ER:AN D FENGUSON LAND

NO. FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS

JAL કાપ્રે EVISED JAN.,