## APPROVED BY PEER GROUP P.A. 345 OF 1990

Saginaw

Property in Sec.

Private Claims \_

## LIBER **1925** PAGE **1154**

P.A. 1970

GINAW COLINTY	SAGINAW COUNTY REMONUMENTATION
GINAW COUNTY	LAND CORNER RECORDATION CERTIFICATE

12-7-94	. (327)	LAND CORNER RECORDATION CER
		Filing Requirement of Act 74, Mich.
For corners in	SURVEY &	
On artis and	20LAF : O	

77 77 77 TE		<b>X</b>
2005 2005	29	Ę C O
MILONES W. SODAK RESISTEN OF DEEDS	9	RECORUED & FILED
	29 AM	S C
Sox	تق	8

REMONUMENTATION IN Corner Code ## Public Land Supply 2 4 1995 T 12N R 3E K-11 COMMISSION **Property Controlling** \_ R . in Section Miscellaneous

Register of Deeds Stamp & File Number

	•		
Duane F. Ledy	, in a field survey onJu	uly 28	, 19 <del>94</del> ,
do hereby certify that unde	r requirements of P.A. 74, Michigan are in conformance with regulation	P.A. of 1970, the corne	er points mentioned
current manual of survey i	nstructions of the United States De	epartment of the Interi	ior, Bureau of Land
	e of a Court of Law and/or that the o	•	

Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded

on this certificate.

Description of original monument and accessories and/or subsequent restoration:

K-11 Set post 80 chains north of K-13, J. Wampler, 1822:

\_ , Recorded Plat \_

36" Pine S 191/2" W 24 links.

18" Maple N 26° W 15 links.

Spicer Eng. noted corner on Western Hills Plat, 1955: L9, P21. Type of monument not indicated.

Spicer Eng. noted corner on Westwood Estates (Sec.26), 1966: L15, P28. Type of monument not indicated.

Hammond recorded corner on survey in 1976 & 1977: L1489, P785 and L1558, P913. Corner found was a 3/4: pipe.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

K-11 Found 3/4" pipe in monument box.

No L.C.R.C.'s recorded this corner.

Found recorded witnesses as follows:

S.W. 108.7' (108.7'R, 108.20'R) to corner of house #1020.

Distances measured compared closely with platted distances on Western Hills Plat. Position of existing monument accepted as best possible location of original corner. Corner accepted by Saginaw County Peer Review Group on December 7, 1994.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-11 Set 3" Saginaw County brass cap on 5/8" x 18" rebar alongside existing %" pipe in monument box.

N 45° W 61.00' to PK nail in utility pole.

34.29' to spike in 10" tree.

S 40° E 59.81' to nail and tag in utility pole.

\$ 40° W 87.80' to spike in 10" pine.

THE OF MICHION

Surveyor's Michigan License No. \_\_

Date

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 197 REVISED MAY 14, 197 REVISED JAH., 198