LIBER 1885 PAGE 1321

SAGINAW COUNTY REMONUMENTATION

DEC 1 5 1993

LAND CORNER RECORDATION CERTIFICATE

llov	24	9 6	12 PH	ıŋ
110 8	47	- C L	12 1 11	J

4. Lot No.

5. Private Claims _

Filing Requirement of Act 74, Mich. P.A. 1970 COMMISSION

FO	r corners in			REUD . GE BEENS
	Saginaw	Located In:	Corner Code ##	REGION A GERBEEDS SACINAL TO SLITY MICH.
1	Public Land Survey	12 N. 4 E.	C-4	Liber 6 Page 141
1.		T R		Line, a regard
	e N	T R		
2.		S R		
	in Section	S I R		
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
	, ,			

Oct./Nov. 93 Ronald C. Prevost in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law: established, re-established, monumented, re-monumented, recovered, found as expressed below:

6 10

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- Description of original monument and accessories and/or subsequent restoration:
 - Post Set by J. Wampler in 1822. C-4 Co. Surveyor H. Cary, 1878, Stone Buried in Road Co. Surveyor H. Cary, 1879, Stone Buried in Road
 - 3/4" Pipe Set by Spicer Eng. Crew, 1954 C-4 NW 34.0 Face 5" Ash SW 97.6 NE Cor. Brick Fnd'n of House

____, Recorded Plat _

- SE 60.1 Face 20" Elm C-4 3/4" Pipe Rec'd Liber 1, Pg. 49, 1971 S.45°W. 36.5 Spike N. Face P. Pole S.50°W. 42.35 Top Fire Plug
- 3/4" Pipe Rec'd Liber 1, Pg. 252 NW 89.51 to SE Cor. block Fnd'n House SW 93.97 to NE cor. block Fnd'n House NW 33.57 Face 18" Alder
- Rec'd Surveys: L 1340 Pg 622 L 1361 Pg 1067 L 1558 Pg 954

L 1612 Pg 1980 L 1643 Pg 1165

- Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - Found 3/4" in Mon. Box (agrees with above), and is accepted as the best available evidence of the position of the original C-4

Ratified by Saginaw County Peer Review Group 9-30-93

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - Set 5/8" x 18" Re-bar with Saginaw Co. Re-Mon Bronze Cap Stamped #24612 in Ex. Mon. Box C-3

Nail & Cap in NW Face P. & T. Pole N.80°E. 50.55 Nail & Cap in S Face 36" Basswood-East 68.50 S.15°W. 117.75 Ctr. Hydrant N.75°W. 28.00 Nail & Cap in E Face T. Pole S.80°W. 93.97 NE Cor. Blk. Fnd'n House N.85°W. 89.63 SE Cor. Blk. Fnd'n House

ROFESSIONAL SURVEYOR

2-612

Signed by .

Surveyor's Michigan License No.

24612

Date 11-24-93

AND OF EAND SURVEYORS JAN. 28, 1971 FORM APPROVED BY MICHIGAN STATE BOAND OF REVISED JAN., 1983