RECORPED & FILED

DEC 1 5 1993

SAGINAW COUNTY REMONUMENTATION

COM	MIS	1 6 mg	CN
A AL BINGS	14113	A 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	7 9 6

LAND CORNER RECORDATION CERTIFICATE

llov 24 2 pz PH '93

For corners in Saginaw		rining nequirement of Act 74, Mich. P.A.		Mileson in a Stark
		Located In:	Corner Code ##	REGISS CONDEEDS SACING FOR STORY RIGH.
1.	Public Land Survey	T12.N. R 4.E T R T R		Liber 6 Page 145
2.	Property Controlling in Section	S T R S T R		
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
	5: 1 6: 1	Recorded Plat		A B C D E F G H I J K L

, 19 <u>93</u> in a field survey on Oct./Nov. I. Ronald C. Prevost do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- 10 11 12
- Description of original monument and accessories and/or subsequent restoration:
 - D-1 Corner Not Set During Government Survey Large Pointed Stone Found by Spicer Eng. 1953

Saginaw Co. Rd. Comm., 1973 Witnessed R.R. Spike

N. 5°W. 53.5 Nail & Cap W, Side P. Pole S.60°E. 193.15 NW Cor. House Foundation 14.37 Corner D-13, T.13 N.-R.4 E. West N.65°W. 151.59 Nail & Cap in SW Side P. Pole D-1 Boat Spike in Mon. Box Rec'd Liber 5, Pg. 41, 1979

14.42 to Mon. Box S.1/4 Cor. Sec. 32, T.13 N.-R.4 E.

N.15°E. 33.45 Face 8" Pine

N.20°W. 55.91 Nail & Cap E. Face P. Pole

9.45 S. Edge Bit. Road South

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - Found 1/2" Boat Spike in Mon. Box, and is accepted as: This position not established by original government surveyors. D-1 The monument is accepted as the best available evidence of the position of the corner.

Ratified by Saginaw County Peer Review Group 9-30-93

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - Set 5/8" x 18" Re-bar with Saginaw Co. Re-Mon Bronze Cap Stamped #24612 in Ex. Mon. Box D-1

SW Cor. Foundation House

N.20°E.

106.98 46.72

Ctr. Hydrant 1/2" Boat Spike in Mon. Box S.01°W.

S.89°W., 14.42 S.1/4 Cor. Sec. 32, T.13 N.-R.4 E STATE OF MICHICAL

Nail & Cap in E. Face P. & T. Pole

N.10°W.

55.94

Nail & cap in E Face T. Pole

N.35°W.

46.78

24612 DE CHIESTAVEADUS TAN FORM APPROVED BY MICHIGAN STATE BOARD WALLE WEED MAY 14, 1975

RONALD C PREVOST **PROFESSIONA** SURVEYOR NO

Surveyor's Michigan License No. .

REVISED JAN., 1983