SURVEY & REMONUMENTATION

MAR 1 8 1998

SAGINAW COUNTY REMONUMENTATION

RECORDED/FILED

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

	rany kequa	ement of Act 14, Mich. P.A	L 13/U	n
For corners in SECTION			1991 251	P 2b P 3: 30
Saginayy (County)	Located In: BLUMFIELD	Corner Code #	MILDR REGIST	ED H. DODAK ER OF DEEDS W COUNTY, MI.
1. Public Land Survey	T <u>12N</u> R6E T R T R	M-5		W COUNTY, MI. 27 Page 479
2. Property Controlling S_ in Section S_ 3. Miscellaneous S_ Property in Sec. S_	T R T R T R T R		Liker	
4. Lot No, Recorde	d Plat		ABCDE	F G H I J K L M
5. Private Claims			2 6 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	-4321
I, Michael J. MacDonald do hereby state that under require mentioned in lines 1 and 2 above required in the current manual of sur Bureau of Land Management or by mentioned in lines 3, 4 and 5 abov Land Surveyors or by a Decree of recovered, found as expressed below	aments of P.A. 74, Michigan were in conformance with vey instructions of the United y a decree of a Court of La were in conformance with of a Court of Law; establis	n P.A. of 1970, the corner poi regulations and rules therefore d States Department of the Interi aw and for that the corner poi the rules of the Michigan Board hed, re-established, monument	as ior, 7 10 10 10 10 10 10 10	-9 -10 -11 -12 - -16 -15 -14 -13 - -21 -22 -23 -24 - -28 -27 -26 -25 -
NOTE: Not more than 2 corners, a on this certificate.	Il in the same town and rang	e, may be recorded	11 32 31 32	33 34 35 36
A. Description of original monumes set post by J. Wampler D. BEECH 12° N 23° E 18 L. BEECH 12° S 16° W 29 L L.C.R.C., L.2,P. 129- 1973- MARTIF RECORDED SURVEY L.767, P.537-L.C.R.C., L.3,P. 205- 1976- MCGINI RECORDED SURVEY L.1499, P.933 RECORDED SURVEY, L.1563, P.804 RECORDED SURVEY, L. 1563, P.42 RECORDED SURVEY, L. 1619, P.42 L.C.R.C., L.1619,P. 539- 19786- R. L.C.R.C., TUSCOLA CO. DENMARK, TUSCOLA CO. PLAT, L. 316, P. 244 RECORDED DURSSEL PLAT	S. N, FND 3/4" BAR IN MON. BO 1975-MCGINNIS, FOUND 3/4 NIS, FND3/4' IRON IN MON1976-HAMMOND, FOUND N 4- 1978- DUNTON, FND MOI 3, 1978- DUNTON, FND MOI 4, 1978- DUNTON, FND MOI OWE, FND MON. BOX WITH: P. 539- 1991- BROWN, FND	OX " IRON IN MON. BOX BOX MON. BOX WITH 3/4" BOLT MENT CALLED OUT, NO WIT. N. BOX WITH 3/4" IRON BAR N. BOX WITH 3/4" IRON 3/4" IRON BAR	APPROVED BY P.A. 345 SAGINAW 6-26-9	
B. Description of corner evider M-5 FOUND 3/4" IRON BAR IN MO RECORDED WITNESSES (L.C.R.C., SURVEY, L.1563, P.423; SURVEY IN THE MONUMENT BOX. MONUM	DNUMENT BOX AT CONSTRU L.2,P. 129; SURVEY L.767, , L. 1619, P.424; L.C.R.C., L	P.537; L.C.R.C., L.3,P. 205; St 1619,P. 539 ; L.C.R.C., DENM	NO OTHER MONUMENTAT JRVEY L.1499, P.933; SUI ARK,P. 539 VERIFY THE I	RVEY, L.1563, P.804; .OCATION OF THE 3/4" BAR
C. Description of monument	for corner and accessories	s established to perpetuate lo	cating the position of th	e corners OF MA
M-5 FOUND 3/4" BAR IN MONUM	IENT BOX, UNABLE TO SET	SAGINAW REMONUMENTATION	I CAP ON THE BAR.	SATE OF MICHIGAN
N 35°E 43.27' SET NAIL AND TAG S 33°E 43.52' SET NAIL AND TAG S 30°W 56.64' SET NAIL AND TAG S 65°W 100.64' SET NAIL AND TAG N 45°W 48.56' SET NAIL AND TAG ON CENTERLINE OF CONC. JOINT E ON CENTERLINE OF CONC. JOINT E	IN NE FACE PP I IN EAST FACE PP IG IN SE FACE PP IS ON TOP OF SE CORNER OF EAST AND WEST ALONG M-1	31		MICHAEL J. MacDONALD PROFESSIONAL SURVEYOR No. 22438
Signed by Mixhael Ga	Me Donald	C	Date 9/25/97	OFESSIONAL SUPPLIES
Surveyor's Michigan License No	224.38			