		ER 1924 PAGE 776	N DDA IFAT
SA	A. 345 OF 1990 SAGINAW COUNTY		Dealii Angrik 34
9-23	2-94 LAND CORNE	R RECORDATION CERTIF	
	SURVEY & Filing Require	ement of Act 74, Mich. P.A	Section 1 SENERDS
For corner	REMONUMENTATION In:	Corner Code #	SACINAW COUNTY MICH.
	(County)		
1 Public	APR 2 4 1995 Land Survey T 13N R 3E	F-13	Liber 6 Page 230
i. Fubiiç	COMMISSION R		Last Gage 230
	T R R		Stoll
2. Proper in Sect	ty Controlling S T R		
3. Miscell	aneous S T R		Register of Deeds Stamp & File Number
Proper	ty in Sec. STR		
4. Lot No 5. Private	Recorded Plat		ABCDEFGHIJKLI
O. Filvate	·		2 6 5 4 3 2 1
	to a field access	Mari 40 04	3 4 7 8 9 10 11 2
I, John H. Rauser , in a field survey on May 19 94 , do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the			d 5 9 -10 11 12
current ma	nual of survey instructions of the United States Departm	nent of the Interior, Bureau of Land	d 6 18 17 16 15 14 13
above were	nt or by a decree of a Court of Law and/or that the corner in conformance with the rules of the Michigan Board of	Land Surveyors or by a Decree of:	
Court of expressed	Law; established, re-established, monumented, re-moelow:	ionumented, recovered, found as	9
NOTE: 1	Not more than 4 corners, all in the same town :	and range, may be recorded	10 30 29 28 27 26 26
	on this certificate.	•	11 32 33 34 35 36
A. Des	cription of original monument and accessories and	d/or subsequent restoration:	13
(F-13)	1973 L.C.R.C. by John W. Martin, P.	al 1822 government sur Surveyor, 1839 during ad Commission 8. #4699, rec. in L. 13 8. #4699 rec. in L. 2,	survey of Saginaw Reserve
B. Des	cription of corner evidence found and/or method a	applied in restoring or reestabl	ishing corner:
(F-13)	Standard S 1/4 cor., Sec. 33, T13N-	R3E	
	Found no evidence of original gover as stated in "A" above and is acceptoriginal corner.	mment corner. Found 3	7/4" pipe in mon. box as per record ble evidence of the position of the
C. Des	cription of monument for corner and accessories	established to perpetuate loca	ting the position of the corner:
(F-13)	Standard S 1/4 cor., Sec. 33, T13N- Reset 5/8" rerod w/brass cap stampe	R3E R3E R3E	ent, P.S. #39096, in existing
	monument box.	· · · · · · · · · · · · · · · · · · ·	
	\$23°W 53.24' Fnd. spike in E. fc.		ote.
	\$23°W 52.94' Fnd. PK NE fc. Utili \$64°W 76.68' Fnd. spike S. fc. Gu		
	S64°W 51.85' F-1, T12N-R3E	-	A SE OF MICHO
	11 117		JOHN H. * RAUSER ************************************
Signed b	1 / My 14. Kan	<u> </u>	Och S SUNVEYORS
Surveyor	s Michigan License No. 39096		FORM APPROVED BY INCHIGAN STATE BOARD OF CANGE LIVEYORE, JAN. 28, 19 REVISED MAY 14, 19