

SURVEY & REMONUMENTATION

LIBER 1 PAGE 382

NOV 19 1993

LAND CORNER RECORDATION CERTIFICATE  
COMMISSION FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

| FOR CORNERS OF--:                          | LOCATED IN--:                                 | CORNER CODE NUMBER |
|--|---|--------------------|
| 1. PUBLIC LAND SURVEY _____                | T. 10 N. <del>10</del> R. 12 E. <del>12</del> | A - 1              |
| 2. PROPERTY CONTROLLING IN SECTION _____   | , T. _____ N. S., R. _____ E. W.              | Seg. #1            |
| 3. MISCELLANEOUS PROPERTY IN SECTION _____ | , T. _____ N. S., R. _____ E. W.              |                    |
| 4. LOT NO. _____, RECORDED PLAT _____      |   |                    |
| 5. PRIVATE CLAIMS _____                    |   |                    |

RECEIVED FOR RECORD  
93 NOV -4 AM 11:55  
LIBER NO. 1 PAGE NO. 382  
ESTHER LEE  
REGISTER OF DEEDS  
SANILAC CO., MICHIGAN  
REGISTER OF DEEDS STAMP AND FILING NUMBER

I, John A Milletics, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on July 6, 1993, 19\_\_\_\_, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

A - 1 Found Monu Box in place in Blacktop as recorded in Liber 4 Page 388 of the Sanilac County Records.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

A - 1  
NW Cor Section 6 T10N-R12E  
Found Monu Box

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A - 1  
NW Cor Section 6 T10N-R12E  
Monu Box in Place  
S45°E 50.50' to a nail in a Power Pole  
S35°W 99.00' to a nail in a Power Pole  
N20°W 16.85' to a nail in a Guard Rail Post

SIGNED BY [Signature] DATE Nov 1, 1993

SURVEYOR'S MICHIGAN REGISTRATION NO. 25859

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

APPROVED AND SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_  
MICHIGAN REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_

