UBER 1 #36E384

NOV 19 1949AND CORNER RECORDATION CERTIFICATE

COMMISSION FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -: LOCATED IN -:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY T. 10 N. R. 12 E.	RECEIVED FOR RECORD
2. PROPERTY CONTROLL- ING IN SECTION—, T, N E	93 NOV -4 AM II: 57
3. MISCELLANEOUS PROPERTY IN SECTION ,T. S., R. W.	LIBER NO. / PAGE NO.384
4. LOT NO, RECORDED PLAT	ESTIER LEE
5. PRIVATE CLAIMS	REGISTER OF DEEDS STAMP AND FILING NUMBER
I,	eld survey on July 5, , 19 93, established, ored as expressed below and in conformance with regulations instructions of the United States Department of the Interior, Furthermore, that the corner points mentioned in lines 3, 4 0, , found, recovered, restored, established or re-established chigan State Board of Registration for Land Surveyors or, by a established restoration: Seequent restoration: Corner M - 1 and K - 1
B. Description of corner evidence found and/or method applied	in restoring or re-establishing corner:
M - 1	
NE Cor Section 1 T10N-R12E Found P.K. Nail	I 1 N. 1/4 Cor Section 1 T10N-R12E No corner found
S30°E 81.60' to a nail in a 24" Maple S45°W 52.85' to a nail in a Tele Pole	L - 1 N 1/4 Cor Section 1 T10N-R12E Monu Box Set S10°W 63.80' to the West end of a 48" culvert S10°E 70.05' to the East end of a 48" culvert
Distance between H = 1	, b - 1 measures 2597.22 reet
SIGNED BY John Millell	DATENov. 1, 1993
SURVEYOR'S MICHIGAN REGISTRATION NO. 25859	- Michigan Michigan
FOR STATE AND UNITED STATES ACENCIES:	S & S S S S S S S S S S S S S S S S S S
SIGNED BY CHIEF OF SURVEY PARTY	DATE Surveyor No. 25859
APPROVED AND SIGNED BY MICHIGAN REGISTERED LAND S	DATE 5.5
SURVEYOR'S MICHIGAN REGISTRATION NO	This onal Sullive