

RECEIVED FOR RECORD

94 DEC 16 AM 9:41

LIBER NO. 2 PAGE NO. 19
ESTHER LEE
REGISTER OF DEEDS
SANILAC CO., MICHIGAN

REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Sanilac
(County)

Located In:

Corner Code #

- 1. Public Land Survey N R 13 E
A - 8
- 2. Property Controlling in Section

- 3. Miscellaneous

- Property in Sec. _____

SURVEY & REMONUMENTATION COMMISSION
APR 10 1995

Register of Deeds Stamp & File Number

- 4. Lot No. _____, Recorded Plat _____
- 5. Private Claims _____

I, John A Milletics, in a field survey on Aug 4, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- A - 8 GLO Notes
- Set Post Sugar 11 N86W 1 1/2, Hem, 40 N61W 23
- Act 74 Form - NONE
- Act 132 Form - NONE
- County Surveyor - NONE
- Road Comm - NONE
- Drain Comm - NONE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- A - 8 W 1/4 Corner Section 19 T10N-R13E
- Found 3/4" Iron in road bed 2'± West of C/L

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- A - 8
- W 1/4 Cor Section 19 T10N-R13E
- Found 3/4" Iron bar
- S80°W 43.17' to a nail in a 8" Cherry
- S75°E 35.10' to a nail in a 12" Cherry
- N45°W 48.58' to a nail in a 6" Elm
- S15°E 71.05' to a nail in a 30 Aspen

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

Approved Peer Board Meeting
Dec. 16, 1994 *gm*

Signed by *John A. Milletics*
Surveyor's Michigan License No. 25859

Date Dec. 5, 1994

