

RECEIVED FOR RECORD

94 DEC 16 AM 9:41

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

LIBER NO. 2 PAGE NO. 20
ESTHER LEE
REGISTER OF DEEDS
SANILAC CO., MICHIGAN

REMONUMENTATION
SURVEY &
REMONUMENTATION
APR 10 1995
COMMISSION

For corners _____
Sanilac _____
(County)

Located In: _____ Corner Code # _____

1. Public Land Survey	T	10	R	13	E	A - 9
	T		R			
	T		R			
	T		R			
2. Property Controlling in Section	S		T		R	
	S		T		R	
3. Miscellaneous Property in Sec.	S		T		R	
	S		T		R	

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, John A Milletics, in a field survey on Aug 4, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
 A - 9 GLO Notes
 Set Post Hemlock 18 S 27W 18, Beech 5 N 39 E 12
 Act 74 Form Liber 1 Page 157
 Act 132 Form Liber 4 Page 806

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 A - 9
 NW Corner Section 30 T10N-R13E
 Found 1/2" Iron

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 A - 9
 NW Cor Section 30 T10N-R13E
 Found 1/2" iron
 S43°51'W 40.96' wooden corner post
 N39°11'W 41.88' 4 x 4 Wood post
 S58°42'E 108.9' to a nail in a Power Pole
 N72°52'E 36.75' to the west face of a Stop Sign

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

Approved Peer Board Meeting
Dec. 16, 1994 *gm*

Signed by *John A Milletics* Date Dec. 5, 1994
 Surveyor's Michigan License No. 25859

