## UBER 1 PAGE 379

## NOV 19 199 LAND CORNER RECORDATION CERTIFICATE

CHON!		7.5	
3 0 k . \$\$17	. 116 .		•

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -: LOCATED IN -:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY T. 10 N. R. 13	RECEIVED FOR RECOR
2. PROPERTY CONTROLL- ING IN SECTION—, T, S., R	F
2 17700712 117717	
PROPERTY IN SECTION, T N. S., R	ESTHER LEE
4. LOT NO, RECORDED PLAT	ESTHER LEE REGISTER OF DEEDS SANILAC CO., MICHIGAN
5. PRIVATE CLAIMS	REGISTER OF DEEDS STAMP AND FILING NUMBER
re-established, monumented, re-monumented, recovered of and rules therefore as required in the current manual of sureau of Land Management or by a decree of a court of and 5 above were, in a field survey on as expressed below and in conformance with the rules of the Decree of a Court of law:  A. Description of original monument and accessories and	· ·
D - 1 Set corner at a equal distance bet no on site evidence of existing corner f	
E - 1 Set corner using distances from C March 25-28, 1903 by Bert R. Walker.	- 1 to G - 1 and survey dated
<ul> <li>B. Description of corner evidence found and/or method a</li> <li>D - 1</li> <li>N 1/4 Cor Section 5 T10N-R13E</li> <li>No Corner Found</li> </ul>	pplied in restoring or re-establishing corner:  E - 1  NE Cor Section 5 T10N-R13E  No Corner Found
C. Description of monument for corner and accessories est D - 1 N 1/4 Cor Section 5 T10N-R13E Monu Box Set South 43.80' to a nail in a 30" Spruce N45°E 63.65' to a nail in a Power Pole N45°W 63.25' to a nail in a Power Pole	E - 1  NE Cor Section 5 T10N-R13E  Monu Box Set  East 4.33' to the SW Cor Section 32 T11N-R13E  N10°E 65.63' to a nail in a Power Pole
SIGNED BY	Nov 4, 1993
SURVEYOR'S MICHIGAN REGISTRATION NO. 258	
FOR STATE AND UNITED STATES AGENCIES:	Sign Sign Sign Sign Sign Sign Sign Sign
SIGNED BY CHIEF OF SURVEY PARTY	John A. Milletics
APPROVED AND SIGNED BY	DATE Land Surveyor TENO. 25859  DATE DATE
MICHIGAN REGISTERED	LAND SURVEYOR