

NOV 19 1993

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

COMMISSION

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 10 N. S., R. 13 E. W.	F - 1, G - 1
2. PROPERTY CONTROLLING IN SECTION	T. _____ N. S., R. _____ E. W.	Seg. 1
3. MISCELLANEOUS PROPERTY IN SECTION	T. _____ N. S., R. _____ E. W.	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

RECEIVED FOR RECORD

93 NOV -4 AM 11:55

LIBER NO. 1 PAGE NO. 380

ESTHER LEE REGISTER OF DEEDS SANILAC CO., MICHIGAN

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, John A Milletics, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on July 12, 1993, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

F - 1 Found R/R Spike in blacktop as recorded in Liber 4 Page 713 of the Sanilac County Records.

G - 1 Found R/R Spike in blacktop as recorded in Liber 4 Page 713 and Liber 3 Page 538 of the Sanilac County Records.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

F - 1
N 1/4 Cor Section 4 T10N-R13E
Found R/R Spike

G - 1
NE Cor Section 4 T10N-R13E
Found R/R Spike

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F - 1
N 1/4 Cor Section 4 T10N-R13E
Monu Box Set
East 5.12' to the S 1/4 Cor Sec 32 T11N-R13E
North 61.75' to a nail in a Power Pole
N10°W 26.00' to the North end of a 12" Culvert

G - 1
NE Cor Section 4 T10N-R13E
Monu Box Set
East 20.05' to the SE Cor Sec 32 T11N-R13E
N45°W 83.70' to the SE Cor of a Bldg
S45°W 69.00' to a nail in a Power Pole

SIGNED BY [Signature] DATE Nov 4, 1993

SURVEYOR'S MICHIGAN REGISTRATION NO. 25859

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

