

1993

## 1 PAGE 423 LIBER

## CREMONUMENTATION LAND CORNER RECORDATION CERTIFICATE

For corners in	Filing Require	ment of Act 74, Mich. P.A.	1970
Sanilac (County)	Located In:	Corner Code ≠	BECEIVED DUD DECORD
<ol> <li>Public Land Survey</li> <li>Property Controlling in Section</li> <li>Miscellaneous Property in Sec.</li> </ol>	T 10N R 13E T R T R T R T R T R T T T R T R T T T T	H - 1	93 DEC 29 AM 10: 53  LIBER AR
	Recorded Plat		- A B C D E F G H I J K L
i. John A Milletic do hereby certify that under rin lines 1 and 2 above were current manual of survey ins Management or by a decree of above were in conformance of Court of Law; established, expressed below:  NOTE: Not more than 4 on this certificat  A. Description of original H - 1	s. in a field survey onDec_1. equirements of P.A. 74, Michigan P.A. of in conformance with regulations and tructions of the United States Departs of a Court of Law and/or that the corner with the rules of the Michigan Board of re-established, monumented, re-m corners, all in the same town and e.  If monument and accessories and ridence on site to the expectations.	19 93 If 1970, the corner points mention trules therefore as required in the nent of the Interior, Bureau of Lapoints mentioned in lines 3, 4 and Land Surveyors or by a Decree of conumented, recovered, found drange, may be recorded for subsequent restoration:	2 6 5 4 3 2 3 4 7 8 9 10 11 11 15 6 6 6 18 17 16 15 14 17 16 15 14 17 16 15 14 17 16 15 14 17 16 15 14 17 17 18 18 18 18 18 18 18 18 18 18 18 18 18
H - 1 N 1/4 Cor Secti			on 3 and the NW Cor Section 3
H - 1 N 1/4 Corner Se Set Monu Box East 34.48' to East 2639.06' to N40°E 38.00' to	the S 1/4 Cor Section to the NE Cor Section 3 of the North End of a 36"	33 CMP	iting the position of the corner:
Signed by	my lallite	Date	Dec. 24, 1993
Surveyor's Michigan Licer	nse No25859		DAM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAM. 28,