

1993

REMONUMENTATION COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Sanilac (County) Located In: Corner Code #
1. Public Land Survey T 10N R 13E L-1, K-1
2. Property Controlling in Section S T R
3. Miscellaneous Property in Sec. S T R

RECEIVED FOR RECORD
93 DEC 29 AM 10:54
REGISTER OF DEEDS
SANILAC CO. MICHIGAN
Register of Deeds Stamp & File Number

- 4. Lot No. , Recorded Plat
5. Private Claims

Grid table with columns A-M and rows 2-13 containing numbers 1-36.

I, John A Millettics, in a field survey on Dec 17, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- L - 1 Found Railroad spike in centerline of pavement, per survey dated 1-26-84 Kay Eng.
K - 1 Found Railroad spike in centerline of pavement, per survey dated 2-5-1990

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- L - 1 N 1/4 Cor Section 1 T10N-R13E Found Railroad spike
K - 1 NW Cor Section 1 T10N-R13E Found Railroad spike

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- L - 1 N 1/4 Cor Section 1 T10N-R13E Set Monu Box North 19.45 to the East leg of a Road Sign N45°E 58.55' to a nail in a Power Pole S40°E 40.40' to a Stop Sign East 82.55' to the S 1/4 Cor Section 35
K - 1 NW Cor Section 1 T10N-R13E Set Monu Box North 19.70' to the East leg of a Road Sign S30°E 38.20' to a Stop Sign N60°E 135.3' to a nail in a Tele Pole East 75.15' to the SE Cor Section 34

Signed by John A Millettics Date Dec. 24, 1993
Surveyor's Michigan License No. 25859