

94 DEC 16 AM 9:41

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

LIBER NO. 2 PAGE NO. 27
ESTHER LEE
REGISTER OF DEEDS
SANILAC CO., MICHIGAN

REMONUMENTATION
SURVEY &
COMMISSION
APR 10 1995
Sanilac (County)

Located In: _____ Corner Code # _____

1. Public Land Survey T 10 NR 14 E L - 11
 T _____ R _____
 T _____ R _____
 T _____ R _____

2. Property Controlling S _____ T _____ R _____
 in Section S _____ T _____ R _____

3. Miscellaneous S _____ T _____ R _____
 Property in Sec. S _____ T _____ R _____

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

Register of Deeds Stamp & File Number

I, John A Milletics, in a field survey on Aug 17, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

L - 11 GLO Notes
Set 1/2 Section Post: Beech 8 S 5 W 24, Sugar 12 N 10 E 13
Act 74 Form NONE
Act 132 Form NONE
Unrecorded Surveys Dated 1-10-1980, Dated 2-19-90, Dated 6-1-81
MDOT Right of Way Book Page 55
Road Comm NONE
Drain Comm NONE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

L - 11
S 1/4 Cor Section 25 T10N-R14E
Found Monu Box - Raised Monu Box during Resurfacing

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L - 11
S 1/4 Cor Section 25 T10N-R14E
Found Monu Box
N50°W 62.35' to a nail in a Wooden Fence Post
S30°E 29.50' to the West End of a 12" CMP
S50°E 41.50' to the East End of a 12" CMP
S45°E 97.50' to a nail in a 18" Twin Maple

	A	B	C	D	E	F	G	H	I	J	K	L	N
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

Approved Peer Board Meeting
Dec. 16, 1994 97



Signed by [Signature]
Surveyor's Michigan License No. 25859

Date Dec 9, 1994