

REMONUMENTATION SURVEY & REMONUMENTATION
 APR 10 1995
 COMMISSION

RECEIVED FOR RECORD

LAND CORNER RECORDATION CERTIFICATE
 Filing Requirement of Act 74, Mich. P.A. 1970

94 DEC 16 AM 9:41

For corners in Sanilac (County)

LIBER NO. 2 PAGE NO. 28
 ESTHER LEE
 REGISTER OF DEEDS
 SANILAC CO., MICHIGAN

Recorded In: _____ Corner Code: #

1. Public Land Survey	T 10 N R 14E	M - 11
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, John A Milletics, in a field survey on Aug 17, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

M - 11 GLO Notes
 Set Post Corner ; Ash 11 N 67 W 23, Maple 5 S 30 W 15
 Act 74 Form NONE
 Act 132 Form NONE

Unrecorded Surveys Survey dated 1-10-1980, Dated 2-19-90
 MDOT Right of Way Book Page 55

Road Comm NONE
 Drain Comm NONE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M - 11
 SE Cor Section 25 T10N-R14E
 Found Monu Box - Raised Monu Box during Resurfacing

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M - 11
 SE Cor Section 25 T10N-R14E
 Found Monu Box
 South 50.00 to a 1/2" Iron bar
 N30°E 85.85 to a nail in a Power Pole
 S30°E 26.30' to a Road Sign
 N30°E 27.20' to a Road Sign
 Monu Box exists on Road Centerline

Approved Peer Board Meeting
 Dec. 16, 1994 *JM*



Signed by John A. Milletics Date Dec 10, 1994
 Surveyor's Michigan License No. 25859