

REMONUMENTATION SURVEY & REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE 94 DEC 16 AM 9:41

Filing Requirement of Act 74, Mich. P.A. 1970

LIBER NO. 2 PAGE NO. 31

Sanilac (County) Located In: Corner Code #

ESTHER LEE REGISTER OF DEEDS SANILAC CO., MICHIGAN

- 1. Public Land Survey T 10N R 15E C - 11
2. Property Controlling in Section S T R
3. Miscellaneous Property in Sec. S T R

Register of Deeds Stamp & File Number

- 4. Lot No. , Recorded Plat
5. Private Claims

Grid table with columns A-N and rows 1-13. Numbers 1-36 are placed in the grid cells.

I, John A Milletics, in a field survey on Aug 18, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

C - 11 GLO Notes
Set Post Corner: Beech 10 S 31 1/2 E 34, Beech 10 N 26 W 22
Act 74 Form NONE
Act 132 Form Liber 3, Page 514
Unrecorded Surveys Dated 5-7-92: Dated 6-11-90
MDOT Right of Way Book Page 55
Road Comm NONE
Drain Comm NONE

Approved Peer Board Meeting Dec. 16, 1994

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C - 11
SE Cor Section 30 T10N-R15E
Found Monu Box
S30°E 87.75 to a nail in a 6" Ash
S40°E 54.00 to a nail in a 6" Locust
N45°W 60.20 to a nail in a 24" Ash
N45°E 47.30 to a Wooden Fence Post
Monu Box exists .6' North of Road Centerline

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C - 11
SE Cor Section 30 T10N-R15E
Found Monu Box
S30°E 87.75 to a nail in a 6" Ash
S40°E 54.00 to a nail in a 6" Locust
N45°W 60.20 to a nail in a 24" Ash
N45°E 47.30 to a Wooden Fence Post
Monu Box exists .60' North of Road Centerline



Signed by [Signature]

Date Dec 10, 1994

Surveyor's Michigan License No. 25859