

94 DEC 16 AM 9:41

REMONUMENTATION SURVEY & REMONUMENTATION AND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Sanilac (County)

APR 10 1995

Located In:

Corner Code #

LIBER NO. 2 PAGE NO. 32  
ESTHER LEE  
REGISTER OF DEEDS  
SANILAC CO., MICHIGAN

1. Public Land Survey **COMMISSION** T 10 N R 15 E D - 11  
 T \_\_\_\_\_ R \_\_\_\_\_  
 T \_\_\_\_\_ R \_\_\_\_\_  
 T \_\_\_\_\_ R \_\_\_\_\_  
 T \_\_\_\_\_ R \_\_\_\_\_
2. Property Controlling S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
 in Section S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_
3. Miscellaneous S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
 Property in Sec. S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
5. Private Claims \_\_\_\_\_

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, John A Milletics in a field survey on Aug 22, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

D - 11 GLO Notes  
Set 1/2 Section Post; Hemlock 12 S 46 E 3, Hemlock 6 N 51 W 16

Act 74 Form NONE  
Act 132 Form Liber 3, Page 207,

Approved Peer Board Meeting  
Dec. 16, 1994 94

MDOT Right of Way Book Page 56

Road Comm NONE  
Drain Comm NONE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

D - 11  
S 1/4 Cor Section 29 T10N-R15E  
Found Monu Box - Raised Monu Box with resurfacing

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D - 11  
S 1/4 Cor Section 29 T10N-R15E  
Found Monu Box  
N40°W 84.20 to a nail in a Power Pole  
N40°E 82.40 to a nail in a Power Pole  
S05°E 47.75 to a nail in a Riser Pole  
S05°W 26.60 to the West leg of a Road Sign



Signed by [Signature]

Date Dec 10, 1994

Surveyor's Michigan License No. 25859