

REMONUMENTATION

AND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

RECEIVED FOR RECORD

94 DEC 16 AM 9:39

LIBER NO. 1 PAGE NO. 479  
ESTHER LEE  
REGISTER OF DEEDS  
SANILAC CO., MICHIGAN

Register of Deeds Stamp & File Number

For corners in

Sanilac

(County)

Located In:

Corner Code #

- |                                       |             |        |
|---------------------------------------|-------------|--------|
| 1. Public Land Survey                 | T 10N R 16E | C - 11 |
|                                       | R           |        |
|                                       | T           |        |
|                                       | R           |        |
| 2. Property Controlling in Section    | S T R       |        |
|                                       | S T R       |        |
| 3. Miscellaneous Property in Sec.     | S T R       |        |
|                                       | S T R       |        |
| 4. Lot No. _____, Recorded Plat _____ |             |        |
| 5. Private Claims _____               |             |        |

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													


I, John A Milletics, in a field survey on Aug 31, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therelore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:  
C - 11 GLO Notes  
Set Post Corner: Maple S40E 14, Birch N 21 W 18  
Act 74 Form NONE  
Act 132 Form Liber 3 Page 521, Liber 3 Page 293  
Unrecorded Surveys Dated 11-12-86, Dated 1-27-89  
MDOT Right of Way Book Page 57  
Road Comm NONE  
Drain Comm NONE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:  
C - 11  
SE Cor Section 30 T10N-R16E  
Found Monu Box - Raised Monu Box during Resurfacing

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  
C - 11  
SE Cor Section 30 T10N-R16E  
Found Monu Box  
S05°W 27.75 to a nail in a Light Pole  
S35°E 38.75 to Centerline of a Fire Hydrant  
N45°W 55.30 to a nail in a Light Pole  
N50°E 50.80 to a gas pipe line post



Approved Peer Board Meeting  
Dec 16, 1994 SM

Signed by John A. Milletics  
Surveyor's Michigan License No. 25859

Date Dec. 11, 1994