

REMONUMENTATION

LIBER

1 PAGE 455

RECEIVED FOR RECORD

94 AUG 12 PM 2:37

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

LIBER NO. 1 PAGE NO. 455  
ESTHER LEE  
REGISTER OF DEEDS  
SANILAC CO., MICHIGAN

For corners in  
Sanilac  
(County)

Located In: Corner Code #

1. Public Land Survey	T 10N R 16E	C - 13
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

I, John A Milletics, in a field survey on July 20, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

C -13 Found 1/2" Iron Bar in gravel Road as per Survey recorded in Liber 2 on Pages 105 and 106 of the Sanilac County Records.

Approved Peer Board Meeting  
Aug. 9, 1994 *[Signature]*  
gm

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C - 13  
SW Corner Section 32 T10N-R16E  
Found 1/2" Iron Bar

SURVEY &  
REMONUMENTATION

SEP 07 1994

COMMISSION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C - 13  
SW Corner Section 32 T10N-R16E  
1/2" Iron Bar  
East 925.68 to the centerline of Pavement  
South 28.40 to the NE Cor of a Michigan Bell Box  
North 28.54 to a nail E side of a Fence Post  
N45°W 41.00 to a nail SW side of a Fence Post

Signed by John A Milletics  
Surveyor's Michigan License No. 25859

Date July 24, 1994