

REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

94 AUG 12 PM 2:36

LIBER NO. 1 PAGE NO. 454
ESTHER LEE
REGISTER OF DEEDS
SANILAC CO., MICHIGAN

For corners in

Sanilac
(County)

Located In:

Corner Code #

- 1. Public Land Survey T 10N R 16E E - 13
 T R
 T R
 T R
- 2. Property Controlling S T R
 in Section S T R
- 3. Miscellaneous S T R
 Property in Sec. S T R

Register of Deeds Stamp & File Number

- 4. Lot No. _____, Recorded Plat _____
- 5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, John A Milletics, in a field survey on July 19, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
E - 13 Found 5/8" Iron bar in gravel road bed as per survey dated 5-28-78 and recorded Liber 3 on Page 616 of the Sanilac County Records

Approved Peer Board Meeting
Aug. 9, 1994 *[Signature]*
[Signature]

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
E - 13
SW Corner Section 33 T10N-R16E
Found 5/8" Iron Bar

SURVEY &
REMONUMENTATION
SEP 07 1994
COMMISSION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
E - 13
SW Corner Section 33 T10-N-R16E
5/8" Iron Bar
N45°E 49.65 to a nail NW side of a Power Pole
S70°W 88.00 to a anil N side of a Fence Post
S20°E 66.60 to the NW cor of a Michigan Bell Box
N75°E 61.60 to stop sign

Signed by *John A Milletics* Date *July 24, 1994*
Surveyor's Michigan License No. 25859