

RECEIVED FOR RECORD

93 DEC 16 PM 2:04

LIBER NO. 1 PAGE NO. 405
ESTHER LEE
REGISTER OF DEEDS
SANILAC CO., MICHIGAN

REMONUMENTATION CORNER

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Sanilac
(County)

Located In:

Corner Code #

- 1. Public Land Survey T 10N R 16E G - 1
 T _____ R _____
 T _____ R _____
 T _____ R _____
- 2. Property Controlling S _____ T _____ R _____
 in Section S _____ T _____ R _____
- 3. Miscellaneous S _____ T _____ R _____
 Property in Sec. S _____ T _____ R _____
- 4. Lot No. _____, Recorded Plat _____
- 5. Private Claims _____

Register of Deeds Stamp & File Number

I, John A. Milletics, in a field survey on Nov 5, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G - 1 Found 1/2" iron bar in gravel road bed, per survey recorded in Liber 4, Page 64 of the Sanilac County Records.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G - 1
NE Cor Section 4 T10N-R16E
Found 1/2" iron bar

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G - 1
NE Cor Section 4 T10N-R16E
Found 1/2" iron bar
N20°E 12.75' to west leg of a Road Sign
N30°E 62.35' to a nail in a Power Pole
N75°W 74.25' to a nail in a 20" Maple
S50°E 49.20' to a nail in a 8" Maple

	A	B	C	D	E	F	G	H	I	J	K	L	N
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

SURVEY &
REMONUMENTATION
1993
COMMISSION

Signed by

John A. Milletics

Date

Dec. 15, 1993

Surveyor's Michigan License No.

25859