

REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

94 AUG 12 PM 2: 36

LIBER NO. 1 PAGE NO. 451
ESTHER LEE
REGISTER OF DEEDS
SANILAC CO., MICHIGAN

For corners in

Sanilac (County)	Located In:	Corner Code #
1. Public Land Survey	T 10N R 16E	K - 13,
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

Register of Deeds Stamp & File Number

- 4. Lot No. _____, Recorded Plat _____
- 5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, John A Milletics, in a field survey on July 18, 191994

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

K - 13 Found 1/2" iron bar in gravel road bed as per survey dated Jan 2, 1979 Sanilac Land Surveying.

Approved Peer Board Meeting
Aug. 9, 1994 *RLK*

JM

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

K - 13
SE Cor Section 35 T10N-R16E
Found 1/2" Iron Bar

**SURVEY &
REMONUMENTATION**

SEP 07 1994

COMMISSION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K - 13
SE Corner Section 35 T10N-R16E
1/2" iron Bar
S65°W 93.50 to a nail N side of a Anchor Pole
S10°W 45.10 to a nail E side of a Power Pole
N45°E 41.30 to a nail NW side of a 24" Catalpa
N40°W 65.50 to a nail E side of a Power Pole

Signed by *John A Milletics*
Surveyor's Michigan License No. 25859

Date *July 24, 1994*