

REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

94 AUG 12 PM 2: 37

LIBER NO. 1 PAGE NO. 458
ESTHER LEE
REGISTER OF DEEDS
SANILAC CO., MICHIGAN

For corners in

Sanilac (County)	Located In:	Corner Code #
1. Public Land Survey	T 10N R 16E	M - 6, M - 7
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

John A Millettics, in a field survey on July 16, 19 94

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
M - 6 Found Moun Box 0.50' East of existing centerline U.S. 25 as shown on Page 35 of the State Highway Right of Way Book

M - 7 Found Monu Box 7.5 East of the existing centerline of U.S. 25 as shown on Page 35 of the State Highway Right of Way Book

Approved Peer Board Meeting
Aug. 9, 1994 *[Signature]*

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M - 6
E 1/4 Cor Section 13 T10N-R16E
Found Monu Box

M - 7
SE Corner Section 13 T10N-R16E
Found Monu Box

SURVEY & REMONUMENTATION

SEP 07 1994

COMMISSION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M - 6
E 1/4 Cor Section 13 T10N-R16E
Monu Box
S40°E 80.50 to a nail N side of a 18" Willow
N80°W 25.70 to a nail N side of a Guard Rail Post
East 50.00 to a 1/2" iron bar
S50°E 81.00 to a nail S side of a 24" Pine

M - 7
SE Cor Section 13 T10N-R16E
Monu Box
S70°W 105.4 to a nail N side of a Power Pole
N45°W 65.80 to a nail N side of a Power Pole
N50°E 71.80 to a nail S side of a Power Pole
S50°E 54.10 to a nail S side of a Power Pole

Signed by *[Signature]*
Surveyor's Michigan License No. 25859

Date July 23, 1994