

REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

94 AUG 12 PM 2:37

LIBER NO. 1 PAGE NO. 458  
ESTHER LEE  
REGISTER OF DEEDS  
SANILAC CO., MICHIGAN

For corners in

Sanilac (County)	Located In:	Corner Code #
1. Public Land Survey	T 10N R 16E	M - 6, M - 7
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

John A Milletics, in a field survey on July 16, 1994,  
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the  
current manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5  
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a  
Court of Law; established, re-established, monumented, re-monumented, recovered, found as  
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded  
on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:  
M - 6 Found Moun Box 0.50' East of existing centerline U.S. 25  
as shown on Page 35 of the State Highway Right of Way Book  
  
M - 7 Found Monu Box 7.5 East of the existing centerline of U.S. 25  
as shown on Page 35 of the State Highway Right of Way Book

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

Approved Peer Board Meeting  
Aug. 9, 1994

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:  
M - 6  
E 1/4 Cor Section 13 T10N-R16E  
Found Monu Box  
  
M - 7  
SE Corner Section 13 T10N-R16E  
Found Monu Box

SURVEY &  
REMONUMENTATION

SEP 07 1994

COMMISSION

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  
M - 6  
E 1/4 Cor Section 13 T10N-R16E  
Monu Box  
S40°E 80.50 to a nail N side of a 18" Willow  
N80°W 25.70 to a nail N side of a Guard Rail Post  
East 50.00 to a 1/2" iron bar  
S50°E 81.00 to a nail S side of a 24" Pine  
  
M - 7  
SE Cor Section 13 T10N-R16E  
Monu Box  
S70°W 105.4 to a nail N side of a Power Pole  
N45°W 65.80 to a nail N side of a Power Pole  
N50°E 71.80 to a nail S side of a Power Pole  
S50°E 54.10 to a nail S side of a Power Pole

Signed by John A Milletics  
Surveyor's Michigan License No. 25859

Date July 23, 1994