

94 AUG 12 PM 2:37

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

LIBER NO. 1 PAGE NO. 460

For corners in

ESTHER LEE
REGISTER OF DEEDS
SANILAC CO., MICHIGAN

Sanilac (County)	Located In:	Corner Code #
1. Public Land Survey	T 10N R 16E	M - 10, M - 11
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

John A Milletics, in a field survey on July 16, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

M - 10 Found Monu Box in new pavement U.S. 25 as recorded in Liber 3 on Page 491

M - 11 Found Monu Box in intersection of U.S 25 and M 90 (Peck Road) as recorded in Liber 3 on Page 491

Approved Peer Board Meeting
Aug. 9, 1994

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M - 10
E 1/4 Cor Section 25 T10N-R16E
Found Monu Box

M - 11
SE Cor Section 25 T10N-R16E
Found Moun Box

SURVEY &
REMONUMENTATION

SEP 07 1994

COMMISSION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M - 10
E 1/4 Cor Section 25 T10N-R16E
Monu Box
S40°W 89.15 to a nail NW side of a Tele Pole
West 52.00 to a nail N side of a Fence Post
N40°W 78.75 to a nail NE side of a Power Pole
S45°E 45.80 to a nail SW side of a Tele Pole
N45°E 39.00 to SW Cor of catch basin

Signed by John A Milletics
Surveyor's Michigan License No. 25859

Date July 24 94