

94 AUG 12 PM 2:37

REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970 LIBER NO. 1 PAGE NO. 461

ESTHER LEE REGISTER OF DEEDS SANILAC CO., MICHIGAN

For corners in

Sanilac

(County)

Located In:

Corner Code #

- 1. Public Land Survey T 10N R 16E M - 12, M - 13
T R
T R
T R
- 2. Property Controlling in Section S T R
S T R
- 3. Miscellaneous Property in Sec. S T R
S T R

Register of Deeds Stamp & File Number

- 4. Lot No. , Recorded Plat
- 5. Private Claims

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

John A Millettics, in a field survey on July 16, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
M - 12 Found Monu Box in pavement U.S 25 as verified by numbers plats in the Village of Lexington.
M - 13 Found Monu Box in paved area of U.S 25 verified by the Meadows Sub as recorded in Liber 4 on Page 1 of the Sanilac County Records.

Approved Peer Board Meeting
Aug. 9, 1994 *[Signature]*

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M - 12
E 1/4 Cor Section 36 T10N-R16E
Found Monu Box

M - 13
SE Cor Section 36 T10N-R16E
Found Monu Box

SURVEY & REMONUMENTATION

SEP 07 1994

COMMISSION

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M -12 E 1/4 Cor Section 36 T10N-R16E Monu Box N85°W 24.90 to a nail S side of a Tele Pole N45°W 55.59 to a nail S side of 24 " Pine East 33.09 to a nail S side of a Anchor Pole S40°E 79.70 to a nail N side of a Power Pole	M -13 SE Cor Section 36 T10N-R16E Monu Box N45°W 57.20 to a nail NE side of a Power Pole S45°W 53.70 to a nail N side of a Tele Pole S45°E 69.45 to a nail SW side of a Power Pole N50°E 47.00 to a stop sign
---	---

Signed by *John A Millettics* Date *July 24 1994*
Surveyor's Michigan License No. 25859