

94 AUG 12 PM 2:37

REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

LIBER NO. / PAGE NO. 461

ESTHER LEE
REGISTER OF DEEDS
SANILAC CO., MICHIGAN

For corners in

Sanilac

(County)

Located In:

Corner Code =#

- 1. Public Land Survey T 10N R 16E M - 12, M - 13
- T _____ R _____
- T _____ R _____
- T _____ R _____
- 2. Property Controlling S _____ T _____ R _____
- in Section S _____ T _____ R _____
- 3. Miscellaneous S _____ T _____ R _____
- Property in Sec. S _____ T _____ R _____

Register of Deeds Stamp & File Number

- 4. Lot No. _____, Recorded Plat _____
- 5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

John A Milletics, in a field survey on July 16, 19 94,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

1. Description of original monument and accessories and/or subsequent restoration:

M - 12 Found Monu Box in pavement U.S 25 as verified by numbers plats in
the Village of Lexington.

M - 13 Found Monu Box in paved area of U.S 25 verified by the Meadows Sub as
recorded in Liber 4 on Page 1 of the Sanilac County Records.

Approved Peer Board Meeting
Aug. 9, 1994 *[Signature]*

2. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M - 12
E 1/4 Cor Section 36 T10N-R16E
Found Monu Box

M - 13
SE Cor Section 36 T10N-R16E
Found Monu Box

**SURVEY &
REMONUMENTATION**

SEP 07 1994

COMMISSION

3. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M -12
E 1/4 Cor Section 36 T10N-R16E
Monu Box
N85°W 24.90 to a nail S side of a Tele Pole
N45°W 55.55 to a nail S side of 24 " Pine
East 33.05 to a nail S side of a Anchor Pole
S40°E 79.70 to a nail N side of a Power Pole

M -13
SE Cor Section 36 T10N-R16E
Monu Box
N45°W 57.20 to a nail NE side of a Power Pole
S45°W 53.70 to a nail N side of a Tele Pole
S45°E 69.45 to a nail SW side of a Power Pole
N50°E 47.00 to a stop sign

Signed by *[Signature]*

Date July 24 1994

Surveyor's Michigan License No. 25859