

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

DEC 16 1996

COMMISSION

FOR CORNERS OF--:	LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____ T. 11 N. R. 12 E.		A - 13, B - 13
2. PROPERTY CONTROLLING IN SECTION _____, T. _____ N. S., R. _____ E. W.		Seg. 1
3. MISCELLANEOUS PROPERTY IN SECTION _____, T. _____ N. S., R. _____ E. W.		
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

RECEIVED FOR RECORD

93 NOV -8 PM 1:39

LIBER NO. 1 PAGE NO. 391  
ESTHER LEE  
REGISTER OF DEEDS  
SANILAC CO., MICHIGAN

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, John A Milletics, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on Aug 21, 1993, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

A - 13 Found Moun Box in Blacktop per survey dated Dec. 1979 checked with field work Aug 21, 1993

B - 13 Found Monu Box in blacktop as recorded in Liber 3 Page 302 of the Sanilac County Records. Corner is also varied by numerous plats in the City of Marlette.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

A - 13  
SW Cor Section 31 T11N-R12E  
Found Monu Box

B - 13  
S 1/4 Cor Section 31  
Found Monu Box

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A - 13  
SW Cor Section 31 T11N-R12E  
Monu Box in place  
S70°W 70.30' to a nail in a Power Pole  
N20°W 41.15' to a Stop Sign  
N30°E 60.85' to a nail in a Power Pole

B - 13  
S 1/4 Cor Section 31 T11N-R12E  
Monu Box in place  
N10°E 75.18' to SW Cor of House  
S25°E 39.77' to a nail in a Power Pole  
N10°E 33.92' to a nail in a 12" Maple

SIGNED BY [Signature] DATE Nov 4, 1993

SURVEYOR'S MICHIGAN REGISTRATION NO. 25859

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_  
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_  
MICHIGAN REGISTERED LAND SURVEYOR

