

LAND CORNER RECORDATION CERTIFICATE

NOV 19 1993

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

COMMISSION

| FOR CORNERS OF--: | LOCATED IN--: | CORNER CODE NUMBER |
|--|---------------|-----------------------|
| 1. PUBLIC LAND SURVEY _____ T. <u>11</u> N. S., R. <u>12</u> E. W. | | G - 13, <u>H - 13</u> |
| 2. PROPERTY CONTROLLING IN SECTION _____, T. _____ N. S., R. _____ E. W. | | |
| 3. MISCELLANEOUS PROPERTY IN SECTION _____, T. _____ N. S., R. _____ E. W. | | |
| 4. LOT NO. _____, RECORDED PLAT _____ | | |
| 5. PRIVATE CLAIMS _____ | | |

RECEIVED FOR RECORD
 93 NOV -8 PM 1:39
 LIBER NO. 1 PAGE NO. 388
 ESTHER LEE
 REGISTER OF DEEDS
 SANILAC CO., MICHIGAN
 REGISTER OF DEEDS STAMP AND FILING NUMBER

I, John A Milletics, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on Aug 21, 1993, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

- A. Description of original monument and accessories and/or subsequent restoration:
 G - 13 Found P.K. nail as recorded in a plat recorded in Liber 3 Slide 266 Sanilac County Records.
 H - 13 Found R/R Spike as recorded in Liber 4 Page 164 of the Sanilac County Records.

- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- | | |
|-----------------------------|--------------------------------|
| G - 13 | H - 13 |
| SW Cor Section 34 T11N-R12E | S 1/4 Cor Section 34 T11N-R12E |
| Found P.K. nail | Found R/R Spike |

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- | | |
|---------------------------------------|-------------------------------------|
| G - 13 | H - 13 |
| SW Cor Section 34 T11N-R12E | S 1/4 Cor Section 34 T11N-R12E |
| Set Monu Box | Set Monu Box |
| S45°E 46.35' to a nail in a Tele Pole | N45°W 35.35' to a nail in 15" Maple |
| S10°W 43.75' to a nail in a 24" Oak | N05°E 29.20' to a nail in 30" Maple |
| N45°W 40.45' to a Stop Sign Post | N75°E 89.30' to a nail in 36" Maple |

SIGNED BY John A Milletics DATE Nov 4, 1993

SURVEYOR'S MICHIGAN REGISTRATION NO. 25859

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

