NOV 2 1 1997

LIBER

2 PAGE 130

RECEIVED FOR RECORD

COMMISSION

REMOUNUMENTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

97 SEP -9 AM 8: 57 2 PAGE NO. 130 LIBER NO.

ESTHER LEE REGISTER OF DEEDS

For corners in

<u>Sanilac</u>	Located In:	Corner Code #		
(County)				
1. Public Land Survey	T_11NR121 TR	<u>B - 13</u>		
Property Controlling in Section Miscellaneous Property in Sec.	TR_ S TR_ S TR_ S TR_ S TR_	deg. 2		

Register of Deeds Stamp & File Number

4. Lot No	, Recorded Plat
5. Private Claims	

John A Milletics, in a field survey on May 21, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A	В	C D	E	F	G	н _	I J	K	L	М
1						$\top$			Į	1
2	- 6	<del> </del> 5	-	4	-	-3 1	$\frac{1}{1}$	?	— 1 1	
3  -		╁╌╁	-+	-+	╫	+-	╁┈┤			
4		1-1	+	— ૄે — I	+	-10 	<u> </u>	1	—1 	2
5		1-1				╁╴		-		
6	-18-	<del> </del> -i	7	—16-	+	-1 <sup>1</sup> 5	—i	4	—-1 	3
7 -		╅╌┧	-+		+			ļ <sup>1</sup>		
8	_19	2	0	_21-		-2 <sup>1</sup> 2	2	: 3—∙ 1	2	4 
9		1-1		-	+		╁╌	-	<del> </del>	
10	30-	-2	9-	2 <sup>2</sup> 8-	-	2 <sup>1</sup> 7 	2	6— 1	2	5— 1
11		╁┤		$-\uparrow$	$\top$	+	1	1		
12	_3¦1~	3	2	—33 	-	3 <del>4_</del> 	3	35— ]	<del> </del> 3	36—- 
73			┖┈┛						1	

A. Description of original monument and accessories and/or subsequent restoration:

B - 13

GLO NOTES

Hemlock 24 NO6°E 20

Hemlock 24 N75°W 34

APPROVED PEER BOARD MEETING Frey 18, 1997 JM

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

B - 13

S 1/4 Corner Section 31 Tl1N-R12E

Found Monu Box in place - removed by Sanilac County Road Comm. during reconstruction of Road - REPLACED using Act 74 recorded in Liber 1 on Page 391

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B - 13

S 1/4 Corner Section 31 Tl1N-R12E

Monu Box with iron and cap

N10°E 75.18 feet to the SW Corner of a House

N40°E 84.37 feet to the SE Corner of a House

S25°E 39.77 feet to a nail in a Power Pole

N10°E 33.92 feet to a nail in a 12" Maple

N70°E 118.23 feet to a nail in a Power Pole

West2635.32'to the NW Corner Section 31

Schalle Signed by\_ Surveyor's Michigan License No. 25859

Aug 11, 1997 Date

Milletics

Land Surveyor No. 25859

ss/onal