## REMONUMENTATION CORNER

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 1 PAGE 398

For corners in	RECEIVED FOR RECORD
Sanilac Located In: Corner Co	93 OEC 15 AM 9: 15
1. Public Land Survey  T 11N R 13E  T R  T R  T R	LIBERTON PAGE NO. 398  ESTABLE LEE  REGISTER OF DEEDS
2. Property Controlling S T R in Section S T R	
3. Miscellaneous       S T R         Property in Sec.       S T R	
Lot No, Recorded Plat      Private Claims	
I,Iohn_A_Milletics , in a field survey onAug_23 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corr in lines 1 and 2 above were in conformance with regulations and rules therefor	2 6 5 4 3 2 1 1 3 4 7 8 9 10 11 12 12 19 93 10 11 12 12 15 14 13 15 14 13 15 14 13 15 14 13 15 14 13 15 14 15 14 15 14 15 14 15 15 14 15 15 16 16 16 16 16 16 16 16 16 16 16 16 16
current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:	
NOTE: Not more than 4 corners, all in the same town and range, may on this certificate.	be recorded 11 12 31 32 33 34 35 36 13
A. Description of original monument and accessories and/or subseque	— <del>;</del> — : : : :
D - 13 Found no evidence of original corner in existence	
E - 13 Found Moun Box in place as recorded in L County Records	iber 3 Page 577 of the Sanilac
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:	
D - 13 S 1/4 Cor Section 32 T11N-R13E	E - 13 SE Cor Section 32 T11N-R13E
Set corner at a equal distance between the SE Cor and the SW cor of the Section (2648.84')	Found Monu Box SURVEY &
	REMONUMENTATION
	1993
	COMMISSION
C. Description of monument for corner and accessories established to	perpetuate locating the position of the corner:
D - 13 S 1/4 Cor Section 32 Tl1N-R13E Set Monu Box	E - 13 SE Cor Section 32 TllN-R13E Found Moun Box
North 62.10' to a nail in a Power Pole West 5.12' to the N 1/4 Cor Section 4(Monu Bo	West 20.05' to the NE Cor Section 4(Monu Box)
Signed by John A. Millette	Date Dec 14, 1993
Surveyor's Michigan License No25859	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971