REMONUMENTATION CORNER

Signed by _

Surveyor's Michigan License No. 25859

LIBER 1 PAGE 410 LAND CORNER RECORDATION CERTIFICATE

Eor	corners in	Filing Require	ment of Act 74, Mich.	P.A. 1970
	Sanilac	i contact to	Corner Codo -tt	PERFIVED TO
	(County)	Located In:	Corner Code ##	RECEIVED FOR RECORD
1.	Public Land Survey	T 11N_ R _13E T R T R T R	<u>F - 13</u>	93 DEC 17 PM 1: 56 LIBER NO. 1 PAGE NO. 410
	Property Controlling in Section Miscellaneous	S T R S T R S T R	Deg.1	REGISTER OF DEEDS SANILAC CO. MICHIGAN
-	Property in Sec.	S T R		Register of Deeds Stamp & File Number
4.	Lat Na.	Recorded Plat		
				A B C D E F G H I J K
do lin fi curi Mar abo Cou exp	nereby certify that under renes 1 and 2 above were rent manual of survey instagement or by a decree of verwere in conformance wirt of Law; established, ressed below:	n, in a field survey on	of 1970, the corner points med rules therefore as required ment of the Interior, Bureau points mentioned in lines 3, I Land Surveyors or by a Decionumented, recovered, for	3 4 7 8 9 10 11 13 13 15 11 15 11 16 15 14 17 16 15 14 17 16 15 14 17 16 17 18 19 19 19 19 19 19 19 19 19 19 19 19 19
NO	TE: Not more than 4 on this certificate	corners, all in the same town an e.	d range, may be recorde	d 11 31 32 33 34 35
Α.	Description of original	monument and accessories and	/or subsequent restoration	on:
• •-	,	o evidence of original	•	
В.	Description of corner F - 13 S 1/4 Cor Secti	evidence found and/or method a on 33°T11N-R13E	pplied in restoring or ree	stablishing corner:
	Set Corner usin			the SE of 34 to the SW of 33
	and a survey do	ne whiti 1304 or perc "	araci	SURVEY & REMONUMENTATION
			·	1993
				COMMISSION
C.	Description of monum	ent for corner and accessories e	stablished to perpetuate	locating the position of the comer:
	F - 13 S 1/4 Cor Secti Set Monu Box N10°W 32.30' to S10°W 31.90' to	on 33 T11N-R13E the North end of a 36" the South end of a 36" to the SE Cor Section 33	'CMP	
D:	Och	A MILLE	Deta	Dec. 15, 1993

_____ Date __