t File a	÷1	_	
JAN	Į.	9	2000

Ja d coarres a exist to

## LIBER

SE	CT	ON
Acres of the Paris,	ا (ا ﴿ بِ	<b>%_</b> //3 ₩

## 1999 REMONUMENTATION PROGRAM LAND CORNER RECORDATION CERTIFICATE RECEIVED FOR RECORD Filing Requirement of Act 74, Mich. P.A. 1970

For	cornere	in	

SANILAC Located In: Corner Code # 1. Public Land Survey TIINR \_14 E

99 NOV 30 AM 9: 03 LIBER ND. 2 PAGE NO. MICHELE VANNORMAN REGISTER OF DEEDS PAGE NO 329 SAHIL AC CO., HICHIGAN

2. Property Controlling

in Section 3. Miscellaneous Property in Sec. S

Register of Deeds Stamp & File Number

4. Lot No. \_, Recorded Plat 5. Private Claims

I, John A. Milletics, in a field survey on Aug. 2, 19 99 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned In lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1	<u>A</u>	B	c	D	E	F	G	H	1	J	ĸ	L	١
		Ĭ			-		1		1	Т		1	_
2		· 5 —	┪┈╴	- 5 – I	+	4-	-	- 3 —		Ż	+	· į –	•••
3	-	╌		- -		<del> </del>		┿	ļ		_ _	1	
4	$\vdash$	7-	-	8-	<del> </del>	9	4	10-	$\downarrow$	 11	1	 12–	
5	$\vdash$	+-	┦	+	┼	+	+	- -	↓	1	1	$\perp$	_
6	<del> -</del> :	i¦8—	+	1/7-	<del> </del> :	   6	-	15—	<del> </del>	1 1,4—	4	 1,3⊷	_
7	<u> </u>	┼	—	┦—		╀	1	Ь.		<u> </u>		L	
8	1	ا ـــوـا	-	 20_	<del> </del>	 21—	_	 22 <u>—</u>	<u> </u>	 23_		 	_
9	_	╀	_	_	<del> </del>	<u> </u>	-	<u> </u>	<u> </u>	_	ļ	Ĺ	
10		0	<del> </del>	 2 <sub> </sub> 9—	<del> </del>	 28	-	 27	<del> </del>	 26—		5	4
11	_	<u> </u>	-	-	-		$\vdash$	↓	ļ	<u> </u>	$\vdash$	<u> </u>	4
12	3	1—	<del>  -</del> :	2-	<del> </del> -3	]  3	$\vdash$	ا 3 <b>4</b> —	3	J 5	<del> </del> :	  6—	4
		Ī	1		1		1		}	l		1	1

A. Description of original monument and accessories and/or subsequent restoration:

A-12 Birch 12 N9W 261/2; Hemlock 12 S23W 30 01d Survey Liber - None L.C.R.C. - None Road Comm. - None Act 132 - None Unrecorded survey dated Aug 1987

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

A-12

W1/4 Corner Section 31 T11N-R14E Found 1/2" Iron in gravel road bed North 2653.78 feet to the NW Corner Section 31 South 2653.78 feet to the SW Corner Section 31 Accepted as best evidence

> APPROVED PEER BOARD MEETING NOV 19,1999

> > AND STATE OF THE S

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A - 12

W 1/4 Corner Section 31 TllN-R14E

1/2" Iron Bar in Gravel Road Bed

Norht 2653.78 feet to the NW Corner Section 31

South 2653.78 feet to the SW Corner Section 31

 $N45^{\circ}E$  56.65 feet to a stop sign

S45°W 75.80 feet to a nail in a Power Pole

West 39.00 feet to a nail in a Fence Post

N60°W 62.22 feet to a nail in a Power Pole

1027 Signed by \_

Nov 3, 1999 Date

Surveyor's Michigan License No. 25859