

REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>Sanilac</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>11N</u> R <u>14E</u>	F - 13
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

RECEIVED FOR RECORD

93 DEC 29 AM 10:55

LIBER 1 PAGE NO. 429
CATHER LEE
REGISTER OF DEEDS
SANILAC CO., MICHIGAN

Register of Deeds Stamp & File Number

I, John A Milletics, in a field survey on Dec 17, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

F - 13

Found Railroad Spike in paved surface, per survey recorded in Liber 3 page 583 of the Sanilac County Records

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F - 13

S 1/4 Cor Section 33 T11N-R14E
Found Railroad Spike

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F - 13

S 1/4 Cor Section 33 T11N-R14E
Set Monu Box
North 44.93' to a nail in a Power Pole
North 22.70' to the west end of a 12" CMP
South 4.00' to the centerline of the paved surface
N45°E 37.35' to the East end of a 12" CMP

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

SURVEY &
REMONUMENTATION

1993

COMMISSION

Signed by John A. Milletics Date Dec 24, 1993
Surveyor's Michigan License No. 25859