REMONUMENTATION

LIBER 1 PAGE 431 LAND CORNER RECORDATION CERTIFICATE

For corners in		ment of Act 74, Mich. P.A. 19	···
Sanilac	Located In-		
(Counly)	Located In:	Corner Code ##	RECEIVED FOR RECORD
I. Public Land Survey	T <u>lin</u> R <u>14E</u> T R T R T R	1 - 13 K - 13	93 DEC 29 AM 10: 55 LIBER K. J
2. Property Controlling	S T R		REGISTER OF DEEDS SANILAG CO . MICHIGAN
in Section . Miscellaneous	S R		State of the High
Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
Lot No.			
Private Claims	Recorded Plat	<u> </u>	ABCDEFGHIJKL
urrent manual of survey instranagement or by a decree of pove were in conformance with our of Law; established, pressed below: OTE: Not more than 4 con this certificate. Description of original L - 13	quirements of P.A. 74, Michigan P.A. of a conformance with regulations and a uctions of the United States Departm a Court of Law and/or that the corner p th the rules of the Michigan Board of Lire-established, monumented, re-mo orners, all in the same town and monument and accessories and/or monument and accessories and/or concerns.	19————————————————————————————————————	2
к - 13	Box in centerline of pay		
K - 13 Found Monu	Box in centerline of pay	ed surface, per survey	y dated 4-27-1977 ng comer:
K - 13 Found Monu Description of corner et L - 13 S 1/4 Cor Section	Box in centerline of pay	red surface, per survey died in restoring or reestablishin K - 13 SW Cor Section 36 T11	y dated 4-27-1977 ng comer: IN-R14E
K - 13 Found Monu Description of corner et L - 13 S 1/4 Cor Section	Box in centerline of pay	red surface, per survey died in restoring or reestablishin K - 13 SW Cor Section 36 T11	y dated 4-27-1977 ng comer:
K - 13 Found Monu Description of corner ex L - 13 S 1/4 Cor Section	Box in centerline of pay	red surface, per survey died in restoring or reestablishin K - 13 SW Cor Section 36 T11	y dated 4-27-1977 ng comer: IN-R14E SURVEY &
Found Monu Description of corner et L - 13 S 1/4 Cor Section	Box in centerline of pay	red surface, per survey died in restoring or reestablishin K - 13 SW Cor Section 36 T11	y dated 4-27-1977 ng comer: IN-R14E SURVEY & REMONUMENTATION
Found Monu : Description of corner ex L - 13 S 1/4 Cor Section Found Monu Box Description of monument L -13	Box in centerline of pay ridence found and/or method app n 36 T11N-R14E	red surface, per survey lied in restoring or reestablishin K - 13 SW Cor Section 36 T11 Found Moun Box blished to perpetuate locating t K -13	y dated 4-27-1977 ng corner: IN-R14E SURVEY & REMONUMENTATION 1993 COMMISSION the position of the corner:
Found Monu : Description of corner ext 13 S 1/4 Cor Section Found Monu Box Description of monument13 S 1/4 Cor Section	Box in centerline of pay ridence found and/or method app n 36 T11N-R14E	red surface, per survey lied in restoring or reestablishin K - 13 SW Cor Section 36 T11 Found Moun Box blished to perpetuate locating to K -13 SW Cor Section 36	y dated 4-27-1977 ng corner: IN-R14E SURVEY & REMONUMENTATION 1993 COMMISSION the position of the corner:
Found Monu : Description of corner ex L = 13 S 1/4 Cor Section Found Monu Box Description of monument L = 13 S 1/4 Cor Section Monu Box N05°E 31.15' to t S05°E 30.00' to t	Box in centerline of pay ridence found and/or method app n 36 T11N-R14E	blished to perpetuate locating to K - 13 SW Cor Section 36 T11 Found Moun Box blished to perpetuate locating to K - 13 SW Cor Section 36 Monu Box MP N45°E 75.50° to a P S05°W 18.75° to to	y dated 4-27-1977 ng corner: IN-R14E SURVEY & REMONUMENTATION 1993 COMMISSION the position of the corner:
Found Monu : Description of corner ext 13 S 1/4 Cor Section Found Monu Box Description of monument13 S 1/4 Cor Section Monu Box N05°E 31.15' to t S05°E 30.00' to t	Box in centerline of pay didence found and/or method app in 36 THN-R14E It for corner and accessories estate 36 THN-R14E The North end of a 24" Counter and of a 24" Counter an	blished to perpetuate locating to K - 13 SW Cor Section 36 T11 Found Moun Box blished to perpetuate locating to K - 13 SW Cor Section 36 Monu Box MP N45°E 75.50° to a P S05°W 18.75° to to	SURVEY & REMONUMENTATION 1993 COMMISSION the position of the corner: T11N-R14E a nail in a Power Pole the East leg of a Road Sign the West end of a 24" CMP