

SURVEY &
REMONUMENTATION

LIBER 1 PAGE 440

1993
REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in COMMISSION

Sanilac (County) Located In: Corner Code-#

1. Public Land Survey	T 11N R 15E	B - 13, A - 13
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

RECEIVED FOR RECORD

93 DEC 29 AM 11:03

ESTHER LEE
REGISTER OF DEEDS
SANILAC CO., MICHIGAN

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, John A. Milletics, in a field survey on Oct 15, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

B - 13
Found Monu Box in centerline of paved surface

A - 13
Found Monu Box in centerline of paved surface

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

B - 13	A - 13
S 1/4 Cor Section 31 T11N-R15E	SW Cor Section 31 T11N-R15E
Found Monu Box	Found Monu Box

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B - 13	A - 13
S 1/4 Cor Section 31 T11N-R15E	SW Cor Section 31 T11N-R15E
Monu Box	Monu Box
N60°W 207.15' to a nail in a Power Pole	North 47.80' to a nail in a Tele Pole
N15°W 180.05' to a nail in a 30" Ash	N70°E 118.85' to the SW Cor of a House
S65°W 72.85' to a Road Sign	N45°W 67.40' to a nail in a 10" Pine

Signed by John A. Milletics Date Dec 24, 1993
Surveyor's Michigan License No. 25859